ford.com

HEADLAMPS - AUTOLAMP

HEADLAMPS - WIPER ACTIVATED

MIRRORS - HTD, PWR GLASS/

MANUAL-FOLD/TURN SIGNALS

TRAILER BRAKE CONTROLLER

TRAILER TOW WIRE HARNESS

ROOF CLEARANCE LIGHTS

TRAILER SWAY CONTROL

EXTERIOR

(ON/OFF)

TOW HOOKS

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

VEHICLE DESCRIPTION

INTERIOR

SUPER DUTY

2024 F550 4X4 CREW CHASSIS XL 203" WB CHASSIS CAB 7.3L DEVCT NA PFI V8 ENGINE

10-SPEED AUTO TORQSHIFT

4.2" PRODUCTIVITY SCREEN

AIR COND, MANUAL FRONT

OUTSIDE TEMP DISPLAY

• PARTICULATE AIR FILTER

UPFITTER SWITCHES

BLACK VINYL FLOOR COVERING

POWER LOCKS AND WINDOWS

STEERING:TILT/TELESCOPE,

CRUISE & AUDIO CONTROLS

026045

EPA DOT Fuel Economy and Environment

HOTSPOT TELEMATICS MODEM BELT-MINDER CHIME HILL START ASSIST DRIVER/PASSENGER AIR BAGS • JEWEL EFFECT HEADLAMPS SECURILOCK® ANTI-THEFT SYS REMOTE KEYLESS ENTRY SOS POST-CRASH ALERT SYS™ • STABILIZER BAR, FRONT/REAR SYNC®4 W/8" SCREEN WARRANTY 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST (MSRP) **PRICE INFORMATION** BASE PRICE \$60,370.00 TOTAL OPTIONS/OTHER 3,580.00


RE F61438

SAFETY/SECURITY

ADVANCETRAC[™] WITH RSC[®]

AIRBAGS - SAFETY CANOPY®

fueleconomy.gov



EXTERIOR OXFORD WHITE

MEDIUM DARK SLATE VINYL


INTERIOR

4-WHEEL ANTILOCK BRAKE SYS

FORDPASS™ CONNECT 5GWI-FI

FUNCTIONAL

RAMP ONE RA5R	RAIL	TOTAL MSRP\$65,945.00Image: Second conductive state of the second conductive state	IFDOW5HN6REF61438 WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive na	
	ITEM #: 13-M002 O/T 1			
This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		SPECIAL ORDER RJ301 N RB 2X 430 002065 09 30 24		To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



1FDOW5HN6 REF61438 NB BU09

www.ford.com/help/privacy-terms/