



ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2026 F350 DRW 4X4 CREW CHAS
LARIAT 179" WB CHASSIS CAB
6.7L POWER STROKE V8 DIESEL
10-SPEED AUTO TORQSHIFT

TE E13477

EXTERIOR
OXFORD WHITE
INTERIOR
BAJA ACTIVEX TRIMMED

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- FOG LAMPS-LED
- HEADLAMPS - AUTOLAMP (ON/OFF)
- LED REFLECTOR HEADLAMPS
- POWERSCOPE TT POWER-FOLD MIRRORS, POWER/HEATED
- REAR WINDOW PRIVACY GLASS W/DEFROST
- ROOF CLEARANCE LIGHTS
- TOW HOOKS
- TRAILER BRAKE CONTROLLER
- TRAILER SWAY CONTROL
- TRAILER TOW WIRE HARNESS

INTERIOR

- 12" CLUSTER DISPLAY
- 1TOUCH UP/DOWN DR/PASS WIN
- DUAL ZONE AUTO CLIMATE CTL
- HEATED STEERING WHEEL
- HTD/VENTILATED FRT SEATS
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- PWR DRIVER AND PASS SEAT
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS
- UPFITTER SWITCHES

FUNCTIONAL

- 5G MODEM
- B&O SOUND SYSTEM
- ELECTROCHROMIC MIRROR
- FORD APP
- HILL START ASSIST
- INTELLIGENT ACCESS W/PUSH BUTTON START
- STABILIZER BAR, FRONT/REAR
- SYNC@4 W/EVR & 12" SCREEN
- VEH INTEGRATION SYS 2.0

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SECURE PKG 1 YR INCLUDED
- SOS POST-CRASH ALERT SYS™
- TIRE PRESSURE MONIT SYS

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

- PREFERRED EQUIPMENT PKG.648A
- 6.7L POWER STROKE V8 DIESEL
- 10-SPEED AUTO TORQSHIFT
- LT245/75R17E BSW ALL-TERRAIN
- 4.10 RATIO LIMITED SLIP AXLE
- FRONT LICENSE PLATE BRACKET
- ALL WEATHER MATS W/O CARPT MAT
- PLATFORM RUNNING BOARDS
- 14000# GVWR PACKAGE
- ENGINE BLOCK HEATER
- SKID PLATES
- 50 STATE EMISSIONS
- SPARE TIRE AND WHEEL
- SIRIUSXM W/360L (3 MOS TRIAL)
- JACK
- SECURICODE KEYLESS KEYPAD
- 350 AMP ALTERNATOR
- EXTRA HEAVY SERVICE SUSPENSION
- ACTIVEX TRMD 40/CONSLE/40 SEAT
- CONN PKG: 1 YR INCL W/FORD APP

(MSRP)

- 10,995.00
- NO CHARGE
- 165.00
- 395.00
- NO CHARGE
- 180.00
- 445.00
- 250.00
- 150.00
- NO CHARGE
- 350.00
- NO CHARGE
- 455.00
- NO CHARGE
- 125.00
- NO CHARGE

PRICE INFORMATION

BASE PRICE	\$68,300.00
TOTAL OPTIONS/OTHER	13,510.00
TOTAL VEHICLE & OPTIONS/OTHER	81,810.00
DESTINATION & DELIVERY	2,795.00

(MSRP)

fueleconomy.gov

Calculate personalized estimates and compare vehicles



The FordPass™ Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.** See in-vehicle settings for connectivity options.

*Based on 1977-2024 CY total sales. **FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes Wi-Fi hotspot.



Insist on Ford Protect! The only extended service plan fully backed by Ford and honored at every Ford dealership in the U.S., Canada and Mexico. See your Ford dealer or visit www.FordOwner.com.



Get Prequalified now at www.ford.com/finance

RAMP ONE

RK34

RAMP TWO

RAIL

ITEM #:

52-R114 O/T 2

TOTAL MSRP \$84,605.00

Scan The QR Code to get more details about this vehicle



This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

TB171 N RB 2X 640 003941 02 17 26

1FD8W3HT4TEE13477



WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.