KIP-UUIOI4 OR 9-NORMAL, NB, 101614, RM021 3071			CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA 273/	
	CLE DESCRIPTION SUPER DUTY 2025 F350 DRW 4X4 CREW CHA XL 179" WB CHASSIS CAB 6.7L POWER STROKE V8 DIESE 10-SPEED AUTO TORQSHIFT	AS EXTERIOR OXFORD WH L INTERIOR	SE CO6963 HITE RK SLATE VINYL	California Air Resources Board Environmen
STANDARD EQUIPMENT INCLUDED A EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - HID, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE MIRCOM EQUIPMENT PKG.640A 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT 17245/75R17E BSW ALL-TERRAIN 4.10 RATIO LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET 1400# GVWR PACKAGE SKID PLATES 50 STATE EMISSIONS PRO POWER ONBOARD - 2KW SNOW PLOW PREP PACKAGE TRAILER BRAKE CONTROLLER CENTER HIGH MOUNT STOP LAMP 40 GAL AFT OF AXLE FUEL TNK EXTERIOR BACKUP ALARM DUAL BATTERY REAR VIEW CAMERA & PREP KIT XL CHROME PACKAGE SACKGLASS DEFROST POWER SLIDING REAR WINDOW FOG LAMPS .EMOTE START SYSTEM .PRIVACY GLASS	INTERIOR 4.2" PRODUCTIVITY SCREEN AIR COND, MANUAL FRONT BLACK VINYL FLOOR COVERING OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING:TILT/TELESCOPE CRUISE & AUDIO CONTROLS UPFITTER SWITCHES (MSRP)	BASE PRIC TOTAL OPT TOTAL VEH	SHEETY/SECURITY 9.040.000000000000000000000000000000000	
	RAMP ONE RD42 RAMP TWO ITEM #: This label is affixed pursuant to th Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inclu	RAIL 74-K301 O/T 2 e Federal Automobile line, License, and Title Fees, ided. Dealer installed	L MSRP \$73,550.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	IFD8W3HTXSEC06963 WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

