KTP-000250 _{CA}	72V 916 6B 2 X LABL ADJ COV PRCS B10	RAMP BUMP 1FDRF3EN8SEC90744	SUPER	MAIL	02 550
	ICLE DESCRIPTION SUPER DUTY 2025 F350 SRW 4X2 REG CHAS XL 145" WB CHASSIS CAB 7.3L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT	SE CO EXTERIOR OXFORD WHITE INTERIOR MEDIUM DARK SLATE VINYL		California Air Reso Envi	ources Board ronmen
STANDARD EQUIPMENT INCLUDED A EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • HEADLAMPS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.630A 10-SPEED AUTO TORQSHIFT 4.30 ELECTRONIC-LOCKING AXLE SPARE TIRE AND WHEEL JACK FRONT LICENSE PLATE BRACKET 10500# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET TRAILER BRAKE CONTROLLER 410 AMP DUAL ALTERNATOR DUAL BATTERY REAR VIEW CAMERA & PREP KIT XL CHROME PACKAGE .FOG LAMPS .REMOTE START SYSTEM	INTERIORFU• 4.2" PRODUCTIVITY SCREEN• 4• AIR COND, MANUAL FRONT• F• BLACK VINYL FLOOR COVERINGH• OUTSIDE TEMP DISPLAY• H• PARTICULATE AIR FILTER• F• POWER LOCKS AND WINDOWS• S	ORDPASS™ CONNECT 5GWI-FI DTSPOT TELEMATICS MODEM ILL START ASSIST EMOTE KEYLESS ENTRY TABILIZER BAR, FRONT/REAR YNC®4 W/8" SCREEN	RAC™ WITH RSC® SAFETY CANOPY® ER CHIME SSENGER AIR BAGS G 1 YR INCLUDED K® ANTI-THEFT SYS CRASH ALERT SYS™ BUMPER / BUMPER POWERTRAIN ROADSIDE ASSIST DIESEL ENGINE (MSRP) \$50,165.00 1,780.00	These ratings are not d For information Protect the emi- Greenhouse Gas F Cleaner Vehicle emissions are a primat California Air Resources Board	on on how to comp vironment. Ch Rating (tailpipe or D D
	ITEM #:	AIL 58 O/T 59 Ford Credit Whether you decid vehicle, you'll find for you. See your do www.ford.com/fin SPECIAL O R167 R 6B 2X 525 0002		WARNING: Operating, servicin vehicle can expose you to cher lead, which are known to the State of To minimize exposure, avoid breathing vehicle in a well-ventilated area and w For more information go to www.P65W	RF3EN8SEC90744 Ing and maintaining a pass micals including engine ex California to cause cance g exhaust, do not idle the vear gloves or wash your h Varnings.ca.gov/passenge

