КТР-001521 СА 9-1	NORMAL, NB, 101521, RG251 4921	ULN W CERT CERT CERT TRD RAMP BUMP C	I 024 CAMP BOOK EXFL ROTA 1348/1
	XL 145" WB CHASSIS CAB C 7.3L DEVCT NA PFI V8 ENGINE INTI	RE E87065 ERIOR DXFORD WHITE ERIOR MEDIUM DARK SLATE VINYL	California Air Resources Board Environment
STANDARD EQUIPMENT INCLUDED AT NO	These ratings are not directly comparable to For information on how to compar		
HEADLAMPS - AUTOLAMP (ON/OFF) HEADLAMPS - WIPER ACTIVATED MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS ROOF CLEARANCE LIGHTS TOW HOOKS TRAILER BRAKE CONTROLLER	NTERIORFUNCTIONAL4.2" PRODUCTIVITY SCREEN- 4-WHEEL ANTILOCHAIR COND, MANUAL FRONT- FORDPASS™ CONNBLACK VINYL FLOOR COVERING- HOTSPOT TELEMATOUTSIDE TEMP DISPLAY- HILL START ASSISTPARTICULATE AIR FILTER- JEWEL EFFECT HEAPOWER LOCKS AND WINDOWS- MANUAL LOCKINGSTEERING:TILT/TELESCOPE,- REMOTE KEYLESS ICRUISE & AUDIO CONTROLS- STABILIZER BAR, FIUPFITTER SWITCHES- SYNC®4 W/8" SCRE	IECT 5GWI-FI ICS MODEM ICS MODEM ADLAMPS HUBS ENTRY BONT/REAR • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • DRIVER/PASSENGER AIR BAGS • SECURILOCK® ANTI-THEFT SYS • SOS POST-CRASH ALERT SYS™ WARRANTY	Protect the environment. Cho Greenhouse Gas Rating (tailpipe only A+ Cleaner
LT275/70R18E BSW ALL TERRAIN 4.30 ELECTRONIC-LOCKING AXLE NC SPARE TIRE AND WHEEL JACK NC FRONT LICENSE PLATE BRACKET NC 10900# GVWR PACKAGE ENGINE BLOCK HEATER 50 STATE EMISSIONS NC	(MSRP)	Image: Constraint of the second se	Vehicle emissions are a primary contributor to climat California Air Resources Board based on this vehicle's
	RAMP ONE		1FDRF3FN8REE87065
	RA5A RAIL RAMP TWO RAIL ITEM #: 71-D870 O/T 2 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.	TOTAL MSRP\$54,690.00Image: State of the	WARNING: Operating, servicing and maintaining a passent vehicle can expose you to chemicals including engine exha lead, which are known to the State of California to cause cancer at To minimize exposure, avoid breathing exhaust, do not idle the en- vehicle in a well-ventilated area and wear gloves or wash your har For more information go to www.P65Warnings.ca.gov/passenger-v

