KTP-000155 99	71 491 <u>78 x</u> x LABL ADJ COV PRCS	B10 RAMP BUMP 1	FDRF3GNXREF26737	SUPER	MAIL	03 403
Ford.com	VEHICLE DESCRIPTION SUPER DUT 2024 F350 DRW 4X2 REG CH XL 169" WB CHASSIS CAB 7.3L DEVCT NA PFI V8 ENGIN 10-SPEED AUTO TORQSHIFT	IAS EXTE OX	RIOR (FORD WHITE	26737		vironmen
STANDARD EQUIPMENT INCLUDE EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.6404 10-SPEED AUTO TORQSHIFT 3.73 RATIO REGULAR AXLE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS 14000# GVWR PACKAGE 50 STATE EMISSIONS CENTER HIGH MOUNT STOP LAMP JACK 40 GAL AFT OF AXLE FUEL TNK 410 AMP ALTERNATOR DUAL BATTERY REAR VIEW CAMERA & PREP KIT XL CHROME PACKAGE .FOG LAMPS .REMOTE START SYSTEM	 HAT BENDE 4.2" PRODUCTIVITY SCREEN AIR COND, MANUAL FRONT BLACK VINYL FLOOR COVERING OUTSIDE TEMP DISPLAY PATICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING: TILT/TELESCOPE, CRUISE & AUDIO CONTROLS UPFITTER SWITCHES 	EUNCTIONAL • 4-WHEEL ANTILOCK BE • FORDPASS™ CONNEL HILL START ASSIST • JEWEL EFFECT HEAD • REMOTE KEYLESS EN • STABILIZER BAR, FRO • SYNC®4 W/8" SCREE	CT 5GWI-FI S MODEM AIRBAGS - BELT-MINE DRIVER/PA SECURILOO SOS POST- SOS POST- 3YR/36,000 5YR/60,000	RAC™ WITH RSC® SAFETY CANOPY® DER CHIME SSENGER AIR BAGS CK® ANTI-THEFT SYS CRASH ALERT SYS™ POWERTRAIN POWERTRAIN ROADSIDE ASSIST 0 DIESEL ENGINE (MSRP) \$49,545.00 1,340.00	For inform	rimary contributor to clim
	State and Local taxes are not	71-P350 O/T 2 to the Federal Automobile basoline, License, and Title Fees,	TOTAL MSRP Scan The QR Cod get more details a this vehicle	ibout it is it	WARNING: Operating, se vehicle can expose you to lead, which are known to the Sta To minimize exposure, avoid bre vehicle in a well-ventilated area For more information go to www.	Prvicing and maintaining a pass o chemicals including engine exits ate of California to cause cance athing exhaust, do not idle the and wear gloves or wash your h P65Warnings ca gov/passenge

