

ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2025 F350 DRW 4X4 REG CHAS
XL 169" WB CHASSIS CAB
7.3L DEVCT NA PFI V8 ENGINE
10-SPEED AUTO TORQSHIFT

SE D71989

EXTERIOR
OXFORD WHITE
INTERIOR
MEDIUM DARK SLATE VINYL

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- HEADLAMPS - AUTOLAMP (ON/OFF)
- HEADLAMPS -WIPER ACTIVATED
- HEADLAMPS-HALOGEN
- MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS
- ROOF CLEARANCE LIGHTS
- TOW HOOKS
- TRAILER SWAY CONTROL
- TRAILER TOW WIRE HARNESS
- WIPERS- INTERMITTENT

INTERIOR

- AIR COND, MANUAL FRONT
- BLACK VINYL FLOOR COVERING
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS
- UPFITTER SWITCHES

FUNCTIONAL

- 4-WHEEL ANTILOCK BRAKE SYS
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- HILL START ASSIST
- REMOTE KEYLESS ENTRY
- STABILIZER BAR, FRONT/REAR
- SYNC®4 W/8" SCREEN

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SECURE PKG 1 YR INCLUDED
- SECURILOCK® ANTI-THEFT SYS
- SOS POST-CRASH ALERT SYS™

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.640A
10-SPEED AUTO TORQSHIFT
LT245/75R17E BSW ALL-TERRAIN
4.30 RATIO LIMITED SLIP AXLE
FRONT LICENSE PLATE BRACKET
PLATFORM RUNNING BOARDS
14000# GVWR PACKAGE
50 STATE EMISSIONS
120V/400W OUTLET
SPARE TIRE AND WHEEL
TRAILER BRAKE CONTROLLER
JACK
40 GAL AFT OF AXLE FUEL TNK
410 AMP DUAL ALTERNATOR
HEAVY SERVICE FRONT SUSPENSION
DUAL BATTERY
REAR VIEW CAMERA & PREP KIT
XL CHROME PACKAGE
.FOG LAMPS
.REMOTE START SYSTEM

(MSRP)

NO CHARGE

165.00

385.00

NO CHARGE

320.00

NO CHARGE

175.00

350.00

300.00

NO CHARGE

NO CHARGE

115.00

125.00

NO CHARGE

515.00

325.00

PRICE INFORMATION

BASE PRICE

\$55,025.00

TOTAL OPTIONS/OTHER


2,775.00

TOTAL VEHICLE & OPTIONS/OTHER

57,800.00

DESTINATION & DELIVERY

2,095.00

	RAMP ONE		TOTAL MSRP \$59,895.00
	RK34	RAIL	
	RAMP TWO	ITEM #: 52-J001 O/T 60	<div><div></div><div>Ford Credit</div><div>Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.</div></div>
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		
			<div>SPECIAL ORDER</div> <div>SE061 N RB 2X 530 003762 05 06 25</div>

California Air Resources Board

Gasoline Vehicle

Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings. For information on how to compare, please see www.arb.ca.gov/ep_label.

Protect the environment. Choose vehicles with higher ratings:

Greenhouse Gas Rating

(tailpipe only)

A+

D

Cleaner

Smog Rating

(tailpipe only)


A+

B

D

Cleaner

Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.



48 YEARS BUILT Ford TOUGH

F-SERIES®


AMERICA'S BEST SELLING TRUCKS

The FordPass™ Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.** See in-vehicle settings for connectivity options.

*Based on 1977–2024 CY total sales.

**FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes WI-FI hotspot.

1FDRF3HN0SED71989



WARNING:

Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

rates may apply. Text HELP for help

www.ford.com/help/privacy-terms/