OHI-000039 _{MI}	48C 905 6B 2 X LABL ADJ COV PRCS	B10 RAMP BUMP 1FDR	RF3HN3RDA00793	SUPER	MAIL	01 293
ford.com	VEHICLE DESCRIPTION SUPER DUT 2024 F350 DRW 4X4 REG CHAR XL 145" WB CHASSIS CAB 7.3L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT	S EXTERIO OXFOI INTERIOF	R RD WHITE	00793		vironmen
STANDARD EQUIPMENT INCLUD EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.6404 10-SPEED AUTO TORQSHIFT LT245/75R17E BSW ALL-TERRAIN 4.30 RATIO LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS 14000# GVWR PACKAGE ENGINE BLOCK HEATER 50 STATE EMISSIONS SNOW PLOW PREP PACKAGE SPARE TIRE AND WHEEL DELETE 40 GAL AFT OF AXLE FUEL TNK 410 AMP ALTERNATOR DUAL BATTERY REAR VIEW CAMERA & PREP KIT XL CHROME PACKAGE .FOG LAMPS .REMOTE START SYSTEM	 HAT BENDE 4.2" PRODUCTIVITY SCREEN AIR COND, MANUAL FRONT BLACK VINYL FLOOR COVERING OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING: TILT/TELESCOPE, CRUISE & AUDIO CONTROLS UPFITTER SWITCHES 	BAS TOT TOT	GWI-FI ODEM PS REAR	AC™ WITH RSC® AFETY CANOPY® R CHIME SENGER AIR BAGS (® ANTI-THEFT SYS RASH ALERT SYS™ BUMPER / BUMPER POWERTRAIN ROADSIDE ASSIST DIESEL ENGINE (MSRP) \$52,345.00 2,100.00	For informa	D D D
	RAMP ONE CP07 RAMP TWO ITEM #: This label is affixed pursuant to the information Disclosure Act. Gase state and Local taxes are not incorptions or accessories are n	CONVOY 48-3192 O/T 59 he Federal Automobile oline, License, and Title Fees, luded. Dealer installed	Whether you decide	RDER	WARNING: Operating, serv vehicle can expose you to c lead, which are known to the State To minimize exposure, avoid breat vehicle in a well-ventilated area ar For more information go to www.P	DRF3HN3RDA00793 vicing and maintaining a passi chemicals including engine ex e of California to cause cancer thing exhaust, do not idle the d wear gloves or wash your h 65Warnings.ca.gov/passenge

