KTP-001831 <sub>NY</sub>	9-NORMAL,NB,101831,SA061 <b>268</b>	30	CERT CERT CERT TRD RAMP BUN	1027 11 CAMP BOOK EXFL ROTA 1405/1
	ICLE DESCRIPTION SUPER DUTY 2025 F350 DRW 4X4 REG CHAS XL 169" WB CHASSIS CAB 7.3L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT	EXTERIOR OXFORD WHIT INTERIOR	SE C21133 TE K SLATE VINYL	Environment
STANDARD EQUIPMENT INCLUDED A EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • HEADLAMPS - HALOGEN • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.640A 10-SPEED AUTO TORQSHIFT 4.30 RATIO LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS	AT NO EXTRA CHARGE INTERIOR • AIR COND, MANUAL FRONT • BLACK VINYL FLOOR COVERING • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS • UPFITTER SWITCHES MORRP NO CHARGE 385.00 NO CHARGE 320.00		\$55,025	A+ D   Cleaner D   Vehicle emissions are a primary contributor to climate   California Air Resources Board based on this vehicle's   3.00   3.00
14000# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SNOW PLOW PREP PACKAGE FORGED ALUMINUM WHEELS-17" 40 GAL AFT OF AXLE FUEL TNK 410 AMP DUAL ALTERNATOR DUAL BATTERY XL CHROME PACKAGE .FOG LAMPS .REMOTE START SYSTEM	NO CHARGE 175.00 250.00 600.00 NO CHARGE 115.00 NO CHARGE 225.00	GG		
	RAMP ONE RB2M RAMP TWO	BAII	MSRP \$59,090.00 Whether you decide to lease or finance you vehicle, you'll find the choices that are right	our
	This label is affixed pursuant to the Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not inclu	44-B110 O/T 60 Ford Credit line, License, and Title Fees, uded. Dealer installed SA061 N	for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passeng vehicle can expose you to chemicals including engine exha lead, which are known to the State of California to cause cancer ar To minimize exposure, avoid breathing exhaust, do not idle the eng vehicle in a well-ventilated area and wear gloves or wash your han For more information go to www.P65Warnings.ca.gov/passenger-v

