RA5B

RAMP TWO

RAIL

ITEM #:
52-B100 O/T 5C

RAMP ONE

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

TOTAL MSRP \$71,040.00

Scan The QR Code to get more details about this vehicle

**SPECIAL ORDER** 

A099 R 6B 2X 630 000976 10 10 25

California Air Resources Board

MAIL

**A**+

Cleaner

Diesel Vehicle

## **Environmental Performance**

032302

1235/1594

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings. For information on how to compare, please see www.arb.ca.gov/ep\_label.

Protect the environment. Choose vehicles with higher ratings:

Greenhouse Gas Rating (tailpipe only)

D

Smog Rating (tailpipe only)

1FDRF3HTX TED06566



Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.





The FordPass™ Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.\*\* See in-vehicle settings for connectivity options.

\*Based on 1977–2024 CY total sales.

\*\*FordPass Connect (optional on select vehicles),
the FordPass App and complimentary Connected
Service are required for remote features (see
FordPass Terms for details). Connected service
and features depend on compatible AT&T
network availability. Evolving technology/cellular
networks/vehicle capability may limit functionality
and prevent operation of connected features.
Connected service excludes Wi-Fi hotspot.



Insist on Ford Protect! The only extended service plan fully backed by Ford and honored at every Ford dealership in the U.S., Canada and Mexico. See your Ford dealer or visit www.FordOwner.com.

**WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

1FDRF3HTXTED06566



Get Prequalified now at www.ford.com/finance