OHI-000061 CA	71B 152 6B 2 X LABL ADJ COV PRCS	B10 RAMP BUMP 1FDUF4GNX		MAIL	027476 445/471
	2024 F450 4X2 REG CHASSIS XL 169" WB CHASSIS CAB 7.3L DEVCT NA PFI V8 ENGIN 10-SPEED AUTO TORQSHIFT	EXTERIOR OXFORD WHI E INTERIOR	RD A37020 ITE RK SLATE VINYL	FUEL EC	ny and Enviro
STANDARD EQUIPMENT INCLUDED EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE DTIONAL EQUIPMENT PKG.650A 10-SPEED AUTO TOROSHIFT 4.88 RATIO REGULAR AXLE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS 16500# GVWR PACKAGE 50 STATE EMISSIONS 1201/400W OUTLET SPARE TIRE AND WHEEL DELETE JACK 410 AMP ALTERNATOR DUAL BATTERY REAR VIEW CAMERA & PREP KIT XL CHROME PACKAGE .FOG LAMPS .REMOTE START SYSTEM	AT NO EXTRA CHARGE P. 4.2" PRODUCTIVITY SCREEN AR COND, MANUAL FRONT BLACK VINYL FLOOR COVERING OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING: TILT/TELESCOPE, CRUISE & AUDIO CONTROLS UPFITTER SWITCHES (MSRP) NO CHARGE NO CHARGE NO CHARGE 175.00 S00 115.00 NO CHARGE 415.00 225.00	TOTAL VEHI		fueleconomy. Calculate personalized estimates and	RED ON
	RAMP ONE RD27 RAMP TWO	RAIL	MSRP \$56,640.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing vehicle can expose you to chemi lead which are known to the State of Ca	4GNXRDA37020 and maintaining a passenger cals including engine exhaust, alifornia to cause cancer and b
	This label is affixed pursuant t Information Disclosure Act. G State and Local taxes are not i options or accessories are no	asoline, License, and Title Fees, ncluded. Dealer installed R095 R	SPECIAL ORDER 6B 2X 435 000061 12 20 24	To minimize exposure, avoid breathing even vehicle in a well-ventilated area and we For more information go to www.P65Wa	exhaust, do not idle the engine ar gloves or wash your hands fi



www.ford.com/help/privacy-terms/