| | CLE DESCRIPTION | | | | |
|--|---|---|--|---|-------------------------------|
| ford.com | 2024 F550 4X2 REG CHASSIS XL 205" WB CHASSIS CAB 7.3L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT | EXTERIOR OXFORD WHITE INTERIOR MEDIUM DARK | | EPA DOT Fuel Economy and Environment FUEL ECONOMY RATING | S NOT |
| STANDARD EQUIPMENT INCLUDED A EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • ROOF CLEARANCE LIGHTS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE PATEOR DEQUIPMENT PKG.660A 10-SPEED AUTO TORQSHIFT 4.88 RATIO LIMITED SLIP AXLE PAYLOAD PLUS PACKAGE UPGRADE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS 1950# GVWR PACKAGE 50 STATE EMISSIONS SPARE TIRE AND WHEEL DELETE 40 GAL AFT OF AXLE FUEL TNK 410 AMP ALTERNATOR EXTERIOR BACKUP ALARM DUAL BATTERY REMOTE START SYSTEM | INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • BLACK VINYL FLOOR COVERING • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, | EUNCTIONAL 4-WHEEL ANTILOCK BRAKE SYS FORDPASS™ CONNECT 5GWI-FI HUL START ASSIST JEWEL EFFECT HEADLAMPS REMOTE KEYLESS ENTRY STABILIZER BAR, FRONT/REAR SYNC®4 W/8" SCREEN PRICE INFORI BASE PRICE TOTAL OPTION TOTAL VEHICLI DESTINATION 8 | \$54,865.00 2,925.00 E & OPTIONS/OTHER 57,790.00 | The For activ (e.g., diagu settin *Base **FordPass the FordPass the FordPass the FordPass Service ar FordPass and feat network ava network sve and preve | <text><image/><image/></text> |
| | ITEM #: | 4310 O/T 59 Haral Automobile | MSRP \$59,785.00 /hether you decide to lease or finance your ehicle, you'll find the choices that are right or you. See your dealer for details or visit www.ford.com/finance. | IFDUF5GN4RDA28027 Image: Servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl Iead, which are known to the State of California to cause cancer and birth defects or other reproductive maintaining exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle for more information go to www.P65Warnings.ca.gov/passenger-vehicle. | apply. Text HELP |

