^{SD} A14333

VEHICLE DESCRIPTION SUPER DUTY

2025 F550 4X4 REG CHASSIS XL 169" WB CHASSIS CAB 6.7L POWER STROKE V8 DIESEL **10-SPEED AUTO TORQSHIFT**

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

ford.com

.FOG LAMPS

.REMOTE START SYSTEM

| EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • HEADLAMPS - HALOGEN • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT | INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • BLACK VINYL FLOOR COVERING • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS • UPFITTER SWITCHES | FUNCTIONAL 4-WHEEL ANTILOCK BRAKE SYS FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM HILL START ASSIST REMOTE KEYLESS ENTRY STABILIZER BAR, FRONT/REAR SYNC®4 W/8" SCREEN | SAFETY/SECURITY • ADVANCETRAC™ Wi • AIRBAGS - SAFETY (• BELT-MINDER CHIM • DRIVER/PASSENGEF • SECURE PKG 1 YR II • SECURILOCK® ANTI • SOS POST-CRASH A WARRANTY • 3YR/36,000 BUMPEF • 5YR/60,000 POWERT • 5YR/60,000 DIESEL | CANOPY® E R AIR BAGS NCLUDED -THEFT SYS LERT SYS™ R / BUMPER RAIN DE ASSIST | |
|---|---|---|---|---|--|
| INCLUDED ON THIS VEHICLE | (MSRP) | | | (MSRP) | |
| OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.660A 6.7L POWER STROKE V8 DIESEL | 10,495.00 | PRICE INFOR BASE PRICE TOTAL OPTION | | \$59,420.00 15,140.00 | fueleconomy. Calculate personalized estimates and |
| 10-SPEED AUTO TORQSHIFT 225/70R19.5G TRACTION TIRES 4.30 RATIO LIMITED SLIP AXLE PAYLOAD PLUS PACKAGE UPGRADE 1 FRONT LICENSE PLATE BRACKET | NO CHARGE 190.00 395.00 1,155.00 NO CHARGE | TOTAL VEHICL DESTINATION | LE & OPTIONS/OTHER & DELIVERY | 74,560.00 2,095.00 | |
| PLATFORM RUNNING BOARDS 19500# GVWR PACKAGE SKID PLATES 50 STATE EMISSIONS | 320.00 100.00 NO CHARGE | | | | |
| 120V/400W OUTLET SPARE TIRE AND WHEEL TRAILER BRAKE CONTROLLER INTERIOR WORK SURFACE | 175.00 350.00 300.00 140.00 | | | | |
| HIGH CAPACITY TRAILER TOW PKG CENTER HIGH MOUNT STOP LAMP JACK 40 GAL AFT OF AXLE FUEL TNK 350 AMP ALTERNATOR | 580.00 100.00 NO CHARGE NO CHARGE NO CHARGE | | | | |
| DUAL BATTERY REAR VIEW CAMERA & PREP KIT XL CHROME PACKAGE | NO CHARGE 515.00 325.00 | | | | |

EXTERIOR OXFORD WHITE

MEDIUM DARK SLATE VINYL

INTERIOR

| RAMP ONE | | TOTAL MSRP | \$76,655.00 | | |
|--|---|--|--------------------------------|--|--|
| RA84 | | Whatharwoud | ecide to lease or finance your | | |
| RAMP TWO | RAIL | | nd the choices that are right | | |
| | ITEM #: 72-5982 O/T 2 | Ford Credit for you. See you www.ford.com | ur dealer for details or visit | WARNING: Op vehicle can exp lead, which are known | |
| Information Disclose State and Local taxe | pursuant to the Federal Automobile ure Act. Gasoline, License, and Title Fees, es are not included. Dealer installed ies are not included unless listed above. | SE081 N RB 2X 530(| 000711 05 08 25 | To minimize exposure, vehicle in a well-ventila For more information g | |

EPA DOT Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT REQUIRED ON THIS VEHICLE

gov

d compare vehicles





The FordPass[™] Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.** See in-vehicle settings for connectivity options.

*Based on 1977-2024 CY total sales. **FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes WI-FI hotspot.



1FDUF5HT3SDA14333

Operating, servicing and maintaining a passenger vehicle, pickup truck, v expose you to chemicals including engine exhaust, carbon monoxide, phtl wn to the State of California to cause cancer and birth defects or other reproductive narm. re, avoid breathing exhaust, do not idle the engine except as necessary, service your tilated area and wear gloves or wash your hands frequently when servicing your vehicle. n go to www.P65Warnings.ca.gov/passenger-vehicle.

rates ma apply. Text HELP for help



www.ford.com/help/privacy-terms/