FUEL ECONOMY RATINGS NOT

REQUIRED ON THIS VEHICLE

EPA Fuel Economy and Environment

E-SERIES

2025 E-350 CUTAWAY SRW SRW 138 WB 7.3L V8 PREMIUM-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL**

SD **D09832**

EXTERIOR OXFORD WHITE **INTERIOR MEDIUM FLINT CLOTH**

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

- AUXILIARY FUEL PORT
- BUMPER, BLACK
- HEADLAMPS AUTOLAMP (ON/OFF)
- INTERVAL WIPERS
- LT245/75R16E BSW A/S TIRES
- **SOLAR TINTED GLASS**

DAYTIME RUNNING LIGHTS

REMOTE KEYLESS ENT/PANIC ALARM

INTERIOR

- AIR CONDITIONING
- AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING
- GLOVE BOX WITH POWERPOINT
- POWERPOINT 12V (FRONT) STEERING - TILT/TELESCOPIC
- TACHOMETER

NO CHARGE

RAMP ONE

RAMP TWO

RA14

- VINYL FRONT HEADLINER
- VINYL SUN VISORS

FUNCTIONAL

- AUX TRANSMISSION COOLER
- BATTERY 78 AMP-HR
- FLEET TELEMATICS MODEM HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

SAFETY/SECURITY

- 3 POINT SAFETY BELTS
- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM DRIVER/PASSENGER AIR BAGS
- ELECTRONIC STABILITY CNTRL
- TIRE PRESSURE MONITOR SYS
- TRACTION CONTROL


WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60.000 ROADSIDE ASSIST









RAIL

24-0207 O/T 59

This label is affixed pursuant to the Federal Automobile

State and Local taxes are not included. Dealer installed

Information Disclosure Act. Gasoline, License, and Title Fees,

options or accessories are not included unless listed above.

fueleconomy.gov Calculate personalized estimates and compare vehicles



TOTAL MSRP \$42,590.00



Whether you decide to lease or finance your vehicle, you'll find the choices that are right Ford Credit for you. See your dealer for details or visit www.ford.com/finance.

SPECIAL ORDER

R942 R 6B 2AI 515 000218 05 22 24

1FDWE3FN0SDD09832

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, pht lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.





www.ford.com/help/privacy-terms