FUEL ECONOMY RATINGS NOT

REQUIRED ON THIS VEHICLE

EPA | Fuel Economy and Environment



2025 E-350 CUTAWAY SRW SRW 138 WB 7.3L V8 PREMIUM-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL** SD **D25749**

EXTERIOR OXFORD WHITE **INTERIOR MEDIUM FLINT CLOTH**

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

- AUXILIARY FUEL PORT
- BUMPER, BLACK
- HEADLAMPS AUTOLAMP (ON/OFF)
- INTERVAL WIPERS
- LT245/75R16E BSW A/S TIRES

REMOTE KEYLESS ENT/PANIC ALARM

SOLAR TINTED GLASS

INTERIOR

- AIR CONDITIONING
- AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING
- GLOVE BOX WITH POWERPOINT
- POWERPOINT 12V (FRONT)
- STEERING TILT/TELESCOPIC
- TACHOMETER VINYL FRONT HEADLINER
- VINYL SUN VISORS

FUNCTIONAL

- AUX TRANSMISSION COOLER
- BATTERY 78 AMP-HR • FLEET TELEMATICS MODEM
- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

SAFETY/SECURITY

- 3 POINT SAFETY BELTS
- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- DRIVER/PASSENGER AIR BAGS
- ELECTRONIC STABILITY CNTRL TIRE PRESSURE MONITOR SYS
- TRACTION CONTROL

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60.000 ROADSIDE ASSIST


fueleconomy.gov

Calculate personalized estimates and compare vehicles











RAMP ONE RA6K RAIL **BAMP TWO** 52-0975 O/T 59

NO CHARGE

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

TOTAL MSRP

\$42,400.00



Whether you decide to lease or finance your vehicle, you'll find the choices that are right Ford Credit for you. See your dealer for details or visit www.ford.com/finance.

SPECIAL ORDER

R029 R 6B 2X 515 000140 09 19 24

1FDWE3FN5SDD25749

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, pht lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



