1FDWE3FN5SDD30238

E-SERIES

EPA Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT

REQUIRED ON THIS VEHICLE

1FDWE3FN5 SDD30238 NB BU09



E-SERIES

2025 E-350 CUTAWAY DRW DRW 138 WB 7.3L V8 PREMIUM-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL** SD **D30238**

EXTERIOR OXFORD WHITE **INTERIOR MEDIUM FLINT CLOTH**

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

- AUXILIARY FUEL PORT
- BUMPER, BLACK
- HEADLAMPS AUTOLAMP (ON/OFF)
- INTERVAL WIPERS
- LT225/75R16E BSW TIRES
- **SOLAR TINTED GLASS**

INCLUDED ON THIS VEHICLE

INTERIOR

- AIR CONDITIONING
- AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING
- GLOVE BOX WITH POWERPOINT
- POWERPOINT 12V (FRONT)
- STEERING TILT/TELESCOPIC
- TACHOMETER VINYL FRONT HEADLINER
- VINYL SUN VISORS

(MSRP)

FUNCTIONAL

- AUX TRANSMISSION COOLER
- BATTERY 78 AMP-HR
- FLEET TELEMATICS MODEM
- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

(MSRP)

SAFETY/SECURITY

- 3 POINT SAFETY BELTS
- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- DRIVER/PASSENGER AIR BAGS ELECTRONIC STABILITY CNTRL
- TRACTION CONTROL

WARRANTY

• 3YR/36,000 BUMPER / BUMPER

(MSRP)

\$38,045.00

4,890.00

42,935.00

1,995.00


- 5YR/60,000 POWERTRAIN
- 5YR/60.000 ROADSIDE ASSIST

fueleconomy.gov Calculate personalized estimates and compare vehicles









RAMP ONE TOTAL MSRP \$44,930.00 **CG07**

CONVOY **BAMP TWO** 16-W698 O/T 59

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

Whether you decide to lease or finance your vehicle, you'll find the choices that are right Ford Credit for you. See your dealer for details or visit www.ford.com/finance.

SPECIAL ORDER

I457 R 6B 2X 515 000088 05 02 25



WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, pht lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.





www.ford.com/help/privacy-terms