OHI-000139 IN	16B 051 6B 2 LABL ADJ COV	XImage: Second seco	1FDWE3FN5TDD11240	E-SERIES	MAIL	030049 489/665
	CLE DESCRIPTION E-SERIES 2026 E-350 CUTAWAY S SRW 138 WB 7.3L V8 PREMIUM-RATE ELEC 6-SPD AOD W/TO	ED ENG. INT	TD D TERIOR OXFORD WHITE ERIOR MEDIUM FLINT VINYL	11240	FUE	conomy and Enviror
STANDARD EQUIPMENT INCLUDED A EXTERIOR • AUXILIARY FUEL PORT • BUMPER, BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • INTERVAL WIPERS • LT245/75R16E BSW A/S TIRES • SOLAR TINTED GLASS INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.780A .STANDARD TRIM 7.3L V8 PREMIUM-RATED ENG. 4.10 LIMITED SLIP AXLE XE6 HIGH-SERIES EXT UPGRADE PKG POWER EQUIPMENT GROUP RAW MATERIALS SURCHARGE FRONT LICENSE PLATE BRACKET 10050# GVWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL MIRRORS,MAN TLR TOW W/PWR GLS	IND EXTRA CHARGE AIR CONDITIONING AM/FM RADIO W/ BLUETOOTI BLACK VINYL FLOOR COVERI GLOVE BOX WITH POWERPOI POWERPOINT - 12V (FRONT) STEERING - TILT/TELESCOPIO TACHOMETER VINYL FRONT HEADLINER VINYL SUN VISORS (MSRP) NO CHARGE 270.00 100.00 615.00 NO CHARGE NO CHARGE NO CHARGE NO CHARGE NO CHARGE NO CHARGE NO CHARGE NO CHARGE 240.00 230.00	NG • FLEET TELEMATICS NT • HILL START ASSIST • TWIN I-BEAM INDE	-HR • 4-WHEEL BRAKING DENDENT • DRIVER/F PENDENT • ELECTRO • TIRE PRE • TRACTION • 3YR/36,00 • 5YR/60,00	SAFETY BELTS ANTI-LOCK DISC SYSTEM ASSENGER AIR BAGS NIC STABILITY CNTRL SSURE MONITOR SYS N CONTROL Y 100 BUMPER / BUMPER 100 POWERTRAIN 100 ROADSIDE ASSIST (MSRI \$40,790.0 1,455.0 DTHER 42,245.0 2,095.0	P) fuelecon Calculate personalized e	SUIRED ON T
	RAMP ONE RC95 RAMP TWO	RAIL ITEM #: 16-6156 O/T 59	TOTAL MSRP Scan The QR Co get more details this vehicle	그는 그는 것이 없는 것이 없 않는 것이 없는 것이 없 않이 없는 것이 없는]	1FDWE3FN5TDD11240
	Information Disclosure State and Local taxes	rsuant to the Federal Automobile e Act. Gasoline, License, and Title Fees, are not included. Dealer installed s are not included unless listed above.	SPECIAL ORDER R208 R 6B 2X 620 000139 05 29 25		To minimize exposure, avoid breathing exhaust, do not idle the engine vehicle in a well-ventilated area and wear gloves or wash your hands fr For more information go to www.P65Warnings.ca.gov/passenger-vehic	

