OHI-000070 99	<b>41A 129 7B X X</b> LABL ADJ COV PRO	S B10 RAMP BUMP	1FDXE4FN3SDD08796	E-SERIES	MAIL	0 263
	CLE DESCRIPTION E-SERIES 2025 E-450 CUTAWAY DRW DRW 176 WB 7.3L V8 PREMIUM-RATED E ELEC 6-SPD AOD W/TOW-H	O ING. INTE	SD D ERIOR XFORD WHITE RIOR IEDIUM FLINT VINYL	08796	EPA DOT FUEL	nomy and En
STANDARD EQUIPMENT INCLUDED A EXTERIOR • AUXILIARY FUEL PORT • BUMPER, BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • INTERVAL WIPERS • LT225/75R16E BSW TIRES • SOLAR TINTED GLASS	T NO EXTRA CHARGE AIR CONDITIONING AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING GLOVE BOX W/ 12V PWR PT POWERPOINT - 12V (FRONT) STEERING - TILT/TELESCOPIC TACHOMETER VINYL FRONT HEADLINER VINYL SUN VISORS	EUNCTIONAL • AUX TRANSMISSION • BATTERY - 78 AMP-+ • FLEET TELEMATICS • HILL START ASSIST • TWIN I-BEAM INDEPI FRONT SUSPENSION	IR • 4-WHEEL A MODEM BRAKING S • DRIVER/PA • ELECTRON • TRACTION • WARRANTY • 3YR/36000 • 5YR/60,000	FETY BELTS NTI-LOCK DISC YSTEM SSENGER AIR BAGS IC STABILITY CNTRL	REQU	JIRED O
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.782A .STANDARD TRIM 7.3L V8 PREMIUM-RATED ENG. 4.56 LIMITED SLIP AXLE XF3 HIGH-SERIES EXT UPGRADE PKG POWER EQUIPMENT GROUP RAW MATERIALS SURCHARGE FRONT LICENSE PLATE BRACKET 14500# GVWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL MIRRORS,MAN TLR TOW W/PWR GLS FRONT MAX GAWR REMOTE KEYLESS ENT/PANIC ALARM	(MSRP) NO CHARGE 270.00 100.00 600.00 NO CHARGE NO CHARGE NO CHARGE 240.00 230.00 NO CHARGE NO CHARGE NO CHARGE		PRICE INFORMATION BASE PRICE TOTAL OPTIONS/OTHER TOTAL VEHICLE & OPTIONS/OT DESTINATION & DELIVERY NOT FOR AMBULANCE FORD WARRANTY IS VO USED AS AN AMBULAN	1,995.00 USE. ND IF	fueleconon Calculate personalized estima	
	RAMP ONE RC95 RAMP TWO	RAIL #: 41-0428 O/T 2	Whether you deci	\$44,430.00 de to lease or finance your the choices that are right dealer for details or visit	WARNING: Operating, se vehicle can expose you to lead, which are known to the Sta	FDXE4FN3SDD08796
	State and Local taxes are no	Gasoline, License, and Title Fees,	B866 A 7BX X 515 000		lead, which are known to the Sta To minimize exposure, avoid bre vehicle in a well-ventilated area a For more information go to www.	te of California to cause canc athing exhaust, do not idle the and wear gloves or wash your P65Warnings.ca.gov/passeng

