OHI-000325 MO 9-NORI	MAL,NB,100325,MG211 <b>276</b>	5	CERT CERT CER	T TRD RAMP BUMI	P CAMP BOOK EXFL 00 276	
Go Further 7.	RIPTION ERIES 22 E-450 CUTAWAY DRW 28 176 WB 28 V8 PREMIUM-RATED ENG. 26 6-SPD AOD W/TOW-HAUL	INTERIO	PR PRD WHITE	0023	<b>EPA</b> DOT Fuel Economy and Env FUEL ECONON	
BUMPER, BLACK HEADLAMPS - AUTOLAMP (ON/OFF) INTERVAL WIPERS LT225/75R16E BSW TIRES SOLAR TINTED GLASS VINY		FUNCTIONAL • AUX TRANSMISSION COC • BATTERY - 78 AMP-HR • FLEET TELEMATICS MOD • HILL START ASSIST • TWIN I-BEAM INDEPENDE FRONT SUSPENSION		Y BELTS LOCK DISC EM NGER AIR BAGS TABILITY CNTRL		
OPTIONAL EQUIPMENT/OTHER     4005-096N01/01/21   LF030Y     PREFERRED EQUIPMENT PKG.782A   .STANDARD TRIM     7.3L V8 PREMIUM-RATED ENG.   NO CH.     4.56 LIMITED SLIP AXLE XF3   2     HIGH-SERIES EXT UPGRADE PKG   1     POWER WINDOWS AND LOCKS GROUP   4     FRONT LICENSE PLATE BRACKET   NO CH.     14500# GVWR PACKAGE   NO CH.     50 STATE EMISSIONS   NO CH.     DRIVER ASSIST TECH PACKAGE   1,3     MIRRORS, MAN TLR TOW W/PWR GLS   2     INSTRUMENT PANEL ELEC MESSAGE   NO CH.     FRONT MAX GAWR   NO CH.     CLOTH BUCKET SEATS   NO CH.     DAYTIME RUNNING LIGHTS   X	70.00 00.00 65.00 RGE RGE 65.00 30.00 RGE ARGE	BA TO TO	• 5YR/60,000 PON • 5YR/60,000 RO/ ICE INFORMATION SE PRICE TAL OPTIONS/OTHER TAL VEHICLE & OPTIONS/OTHEF STINATION & DELIVERY	ADSIDE ASSIST (MSRP) \$36,835.00 2,705.00	Calculate personalized estimates and compare vehicles	
	RAMP ONE RAGP RAMP TWO	<b>BAII</b>	Whether you decide to	<b>40,835.00</b> D lease or finance your choices that are right		
	This label is affixed pursuant to the Information Disclosure Act. Gaso State and Local taxes are not inclu- options or accessories are not inclu-	21-U171 O/T 5C FORM ne Federal Automobile line, License, and Title Fees, uded. Dealer installed	GREDIT Venicle, you it find the for you. See your deale www.ford.com/financ SPECIAL OR IG211 N RB 2X 215 00032	er for details or visit re. <b>DER</b>	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ext lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the evehicle in a well-ventilated area and wear gloves or wash your he For more information go to www.P65Warnings.ca.gov/passenger	

