МІС-006360 тх	9-NORMAL, NB, 106360, RL071 927	6 320241119 2090	ULCUWTXCERT CERT CERTTRDRAMP BUMP (	CAMP BOOK EXFL ROTA 1148
Ford.com	VEHICLE DESCRIPTION BRONCO 2024 OUTER BANKS 4-DOOR 4X OUTER BANKS - 5 PASSENGER 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	OXFORD WHI INTERIOR	RL <b>B45102</b> ITE NYL GRAY/NAVY STS	EPA DOT Fuel Economy and Env Fuel Economy MPG Small SUVs The best ver
STANDARD EQUIPMENT INCLUDE EXTERIOR • EASY FUEL® CAPLESS FILLER • FENDER TIE-DOWN HOOKS • GRILLE-BLK/BRONCO WHITE • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LED • TOW HOOKS-FRT (2)/REAR (1)	INTERIOR • 1TOUCH UP/DOWN DR/PASS WIN • 60/40 SPLIT FOLD REAR SEAT • A/C, DUAL ZONE CLIMATE CTL	EUNCTIONAL • 12"LCD CTR STACK TOUCHSCRN • AUTO START STOP TECH • BRAKES, 4-WHEEL DISC/ABS • FORD CO-PILOT360™ • FORDPASS™ CONNECT • FRONT STABILIZER BAR • HILL START ASSIST • MID PACKAGE • PUSH-BUTTON START • SIRIUSXM® W/360L- NA AK&HI • SYNC®4 W/EVR • TER MGMT W/G.O.A.T. MODES® • TOOL KIT- DOOR/TOP REMOVAL	SAFETY/SECURITY         • ADVANCETRAC™ WITH RSC®         • AIRBAGS-FRNT (DUAL STAGE)         & SIDE IMPACT/SAFETY         CANOPY® SYSTEM (ALL ROWS)         • BELT-MINDER CHIME         • CHILD SAFETY REAR DR LOCKS         • ELCTR STABILITY/TRACTN CTL         • INDIV TIRE PRESS MONIT SYS         • LATCH CHILD SAFETY SYSTEM         • PERIMETER ALARM         • PERSONAL SAFETY SYSTEM™         • MARRANTY         • 3YR/36,000 BUMPER / BUMPER         • SYR/60,000 ROADSIDE ASSIST	Level to the average new vehicle gets 28 MPG and costs \$9,75 Actual results will vary for many reasons, including driving corr vehicle. The average new vehicle gets 28 MPG and costs \$9,75 best on 15,000 miles
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 314A •OUTER BANKS SERIES •HIGH/LUX PACKAGE •360-DEGREE CAMERA •ADAPTIVE CRUISE CONTROL •HEATED STEERING WHEEL •WIRELESS CHARGING PAD OPTIONAL EQUIPMENT/OTHER P255/70R18 A/T TIRES (32") 3.73/REAR AXLE-OPEN DIFF FRONT AXLE-OPEN DIFFRNTL AM/FM,10 SPKRS,SDARS CNCTD NAV (1-YEAR SUB INC) 18" MCHNED BLK-PNTD ALUM WHL HARD TOP,GRAY MOLDED-IN-COLO .SOUND DEADENING HEADLINER .FRT ROW TOP PANEL STORAGE BA FRONT LICENSE PLATE BRACKET AUXILIARY SWITCHES	DR 2,190.00			Description by both three per year of climate change and smog. <b>Gueleconogy</b> Calculate personalized estimates and compare vehicles <b>GOVERNMENT 5-STAR SAFETY Overall Vehicle Score Based on the combined ratings of frontal, side and rollover.</b> Should ONLY be compared to other vehicles of similar size and <b>Frontal</b> Driver <b>Crash</b> Passenger         Based on the risk of injury in a frontal impact.         Should ONLY be compared to other vehicles of similar size and <b>Side</b> Front seat <b>Side</b> Front seat <b>Based on the risk of injury in a side impact</b> .         Should ONLY be compared to other vehicles of similar size and <b>Side</b> Front seat <b>Rear seat</b> Not Rational models         Based on the risk of injury in a side impact.         Should ONLY be compared to other vehicles of similar size and <b>Side</b> Front seat <b>Rear seat</b> Not Rational models         Based on the risk of injury in a side impact. <b>Based on the risk of rollover in a single-vehicle crash</b> .         Star ratings range from 1 to 5 stars (******), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-42
	RAMP ONE RPTB RAMP TWO	RAIL	<b>MSRP \$55,250.00</b> Whether you decide to lease or finance your vehicle, you'll find the choices that are right	1FMDE8BH2RLB45102
	This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not includ options or accessories are not included options or accessories are not included options.	2-1650 O/T 2 Federal Automobile ne, License, and Title Fees, led. Dealer installed RL071 N	RB 2X 450 006360 11 07 24	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

