	LE DESCRIPTION EXPEDITION 2023 EXPED. PLATINUM 4X2 PLATINUM 7-PASSENGER	ЕХТ	PE A6	5479	EPA DOT Fuel Economy and En Fuel Economy
ford.com	3.5L ECOBOOST V6 ENGINE 10SPD AUTO TRANS W/SLCT	INT	ERIOR DNYX LEATHER-TRIM SEATS		MPG. The Standard MPG. The
STANDARD EQUIPMENT INCLUDED AT	NO EXTRA CHARGE				
EXTERIOR • FWD FACING SPOTLIGHT-RH/LH • GRILLE-SILVER LINING MESH • HEADLAMPS -WIPER ACTIVATED • HEADLAMPS-LED REFLECTOR W/LED SIGNATURE LIGHTING • LIFTGATE - HANDS-FREE • MIRRORS-PWR/HTD/AUTO-FOLD SIG/APRCH LAMP/MEM/AUTODIM • PANORAMIC VISTA ROOF® • ROOF RAILS - CHROME • RUNNING BOARD-PWR DEPLOY • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • WIPERS - RAIN-SENSING • ZONE LIGHTING	INTERIOR • 110V/150W AC POWER OUTLET • 2ND ROW HEATED SEATS • 2ND ROW PWR FOLDING TIP-AND-SLIDE SEATS • AMBIENT LIGHT/ILLUM ENTRY • HTD LTHR WRAPPED STR WHL W/CRUISE AND AUDIO CTRLS • HTD/VENTILATED FRT SEATS • PEDALS-PWR ADJ W/MEMORY • POWERFOLD 3RD ROW SEAT • PWR TILT/TEL STR COL W/MEM • TRI-ZONE AUTO CLIMATE CTRL	EUNCTIONAL • 360-DEGREE CAME • ADVANCED CARGO • AUDIO -REAR SEAT • B&O UNLEASHED, 2 • CLASS IV TRLR TOV • CNCTD BLT-IN NAV • ENHANCED ACTV N • FORD BLUECRUISE • FORD CO-PILOT360 • FORDPASS™ CONN HOTSPOT TELEMAT • IP CLSTR 12.4" DIG • SIRIUSXM® W/360L • SYNC®4A W/EVR & • WIRELESS CHARGII	MANAGER CONTROLSADVANCETRA AIRBAGS - DU22 SPKRAIRBAGS - DU22 SPKRAIRBAGS - SAV PREP PAK (3-YR INC)INDIV TIRE PROISE CTRL 1.0(3 YRS)INDIV TIRE PROISE CTRL 1.0(3 YRS)LATCH CHILD1.0(3 YRS) IMACTIVE2.0PERIMETER AIIMACTIVE2.0 IECT 4GWI-FI ICS MODEM FL SCRNSOS POST-CRTI SCRN - NA AK&HIWARRANTY15.5" SCRN NG PADSYR/36,000 BL	CURITY PACK C™ WITH RSC® AL STAGE FRONT FETY CANOPY® DE IMPACT ESS MONIT SYS SAFETY SYSTEM LARM JARM JART ALERT ASH ALERT SYS™	combined city/hwy city highway 5.3 gallons per 100 miles Annual fuel COSt \$2,350 Line vehicle emits 4 distributing fuel also
INCLUDED ON THIS VEHICLE	(MSRP)			(MSRP)	Actual results will vary for many reasons, including driving vehicle. The average new vehicle gets 28 MPG and costs \$8 based on 15,000 miles per year at \$2.95 per gallon. MPGe is emissions are a significant cause of climate change and smo
 EQUIPMENT GROUP 600A PLATINUM SERIES RUNNING BOARDS, STAINLESS PANORAMIC VISTA ROOF TRI-ZONE ELECTRONIC TEMP CNTR B&O PRM SOUND/SIRIUS/SYNC4/HD CCD W/SUSP ROAD PREVIEW REMOTE START SYSTEM SECOND ROW HEATED SEATS 3RD ROW 60/40 POWERFOLD SEAT PRIVACY TINT REAR GLASS ADVANCED CARGO MANAGER ZDATOMOLE YEAR STAR WHITE MET TRI-COAT .P285/45R22 A/S BSW TIRES ND ROW WINDOW ONE TOUCH REMOV 2ND ROW CAPTAIN CHAIR SEATS 22" 6-SPK POLISHED ALUM WHL LUX LEATHER TRIM W/ MCS DELETE 15.5 LCD SCREEN W/TOUCH CAP HANDS FREE LIFTGATE REMOVAL ACTIVE PARK ASSIST 2.0 REMOVAL FRONT LICENSE PLATE BRACKET 	995.00 - 50.00 NO CHARGE 1,250.00 - 300.00 NO CHARGE NO CHARGE - 355.00 NO CHARGE		PRICE INFORMATION BASE PRICE TOTAL OPTIONS/OTHER TOTAL VEHICLE & OPTIONS/OTHE DESTINATION & DELIVERY	\$85,815.00 1,540.00	Side Frontal Driver * * * Based on the combined ratings of frontal, side and rollover * * * Should ONLY be compared to other vehicles of similar size Frontal Driver * * * Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size Eased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size Based on the risk of injury in a side impact. Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (******), Source: National Highway Traffic Safety Adminy www.safercar.gov or 1-888-327
	RAMP ONE RK34 RAMP TWO	RAIL #: 52-Z700 O/T 2	Whether you decide t	89,250.00 to lease or finance your e choices that are right ler for details or visit	IFMJK1L86PEA65479 WARNING: Operating, servicing and maintaining a provide the state of California to cause car be state of California to cause ca
	State and Local taxes are not	asoline, License, and Title Fees,	PH111 N RB 2X 350 00131		lead, which are known to the State of California to cause car To minimize exposure, avoid breathing exhaust, do not idle t vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passe

