СНІ-006559 тх	9-NORMAL,NB,106559,SC181 414	2 120250327 6464	UTC U W TX CERT CERT CERT TRD RAMP BUMP (CAMPBOOKEXFLROTA 0
ford.com	EHICLE DESCRIPTION EXPLORER ACTIVE RWD 2025 EXPLORER ACTIVE RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	INTERIOR	SG B67997 MET TRI-COAT ACTIVEX SEATS	EPA DOT Fuel Economy and En Fuel Economy MPG. The b
STANDARD EQUIPMENT INCLUDER EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO LED • MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • REAR SPOILER, BODY COLOR • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS-LED • TRAILER SWAY CONTROL • VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR STAR WHITE MET TRI-COAT .18" SILVER PAINTED ALUM WHLS .P255/65R18 A/S BSW TIRES 50 STATE EMISSIONS ACTIVE COMFORT PACKAGE .REMOTE START SYSTEM .LED FOG LAMPS .UNIVERSAL GARAGE DOOR OPENER .HEATED STEERING WHEEL .LED SIGNATURE LIGHTING .8-WAY POWER PASSENGER SEAT FRONT LICENSE PLATE BRACKET	NTERIOR 912.3" LCD DIGITAL CLUSTER 912.3" LCD DIGITAL CLUSTER 910.000 HOLD FLAT 920.000 HOLD FLAT 920.000 HOLD FLAT 920.000 HOLD FLAT SOLAT 921.000 HOLD FLAT SOLAT 920.000 HOLD FLAT SOL		\$39,855.00	Image: Additional state of the state of
	RAMP ONE CH7L		. MSRP \$45,605.00	www.safercar.gov or 1-888-327-4 1FMUK7DH7SGB67997
	ITEM #: 5		Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance
	This label is affixed pursuant to the Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inc	line, License, and Title Fees, Ided. Dealer installed SC181 N	RB 2X 555 006559 03 18 25	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

