CHI-006154 AL	9-NORMAL, NB, 106154, SD291 2696	6 120250510 4938	UTC U W AL CERTCERTCERT TRD RAMPBUMPCAM	02 PBOOKEXFLROTABATT 1627/
ford.com	EHICLE DESCRIPTION EXPLORER ST-LINE RWD 2025 EXPLORER ST-LINE RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	INTERIOR	SG C07457 MET TRI-COAT E CLOTH	EPA DOT Fuel Economy and Env Fuel Economy MPG. The best
STANDARD EQUIPMENT INCLUDER EXTERIOR • 'EXPLORER' HOOD BADGING • CLASS III TRAILER TOW PKG • CASY FUEL® CAPLESS FILLER • GRILLE - BLACK MESH INSERT • HEADLAMPS - AUTO LED • LED SIGNATURE LIGHTING • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • UNIQUE ST-LINE BADGING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR STAR WHITE MET TRI-COAT .20" MACH ALUM WHLS W/PNTD PKT .P255/55R20 A/S BSW TIRES BLUECRUISE EQUIP: 90DAY TRIAL 50 STATE EMISSIONS KEYLESS ENTRY KEYPAD MINI SPARE AND JACK KIT FRONT LICENSE PLATE BRACKET	 Internet 12.3" LCD DIGITAL CLUSTER 14.00CH UP/DOWN DR/PASS WIN 15.00CH ROW HEATED SEATS 16.00CH RURAPPED STEERING WHEEL W/MOUNTED CONTROLS AND TILT/TELE STR COLUMN 10.00CH RDRIVER'S SEAT 10.00CH RORS SEAT 10.00CH RORS SHIFT DIAL 10.01CH GARAGE DOOR OPENER 10SB-C - ALL ROWS 		\$44,595.00	Image: Additional state of the state of
	ITEM #:		MSRP \$47,840.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-423 IFMUK7KH8SGC07457 WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not includ options or accessories are not includ	Federal Automobile ne, License, and Title Fees, ed. Dealer installed SD291 N	RB 2X 560 006154 04 29 25	lead, which are known to the State of California to cause cancer a To minimize exposure, avoid breathing exhaust, do not idle the er vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger

