СНІ-000016 РА	4-REBILL,NB,200016,SE162 24	53 120250416 1333	UTC U W PA CERTCERTCERT TRD RAMPBUMPCAM	PBOOKEXFLROTABATT 02
ford.com	EHICLE DESCRIPTION EXPLORER ACTIVE 4WD 2025 EXPLORER ACTIVE 4WD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSIO	EXTERIOR AGATE BLAC INTERIOR DN DARK SPACE	SG B87755 K METALLIC E GRAY CLOTH SEATS	EPA DOT Fuel Economy and Env Fuel Economy PL 22 MPG Standard SL MPG. The b
STANDARD EQUIPMENT INCLUDEI EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO LED • MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • REAR SPOILER, BODY COLOR • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS-LED • TRAILER SWAY CONTROL • VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A OPTIONAL EQUIPMENT/OTHER .P255/65R18 A/S BSW TIRES 2ND ROW CAPTAIN'S CHAIRS 50 STATE EMISSIONS 18" SILVER PAINTED ALUM WHLS MINI SPARE AND JACK KIT FRONT LICENSE PLATE BRACKET	Arno Extra Charge Present a state of the st		 AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® INDIV TIRE PRESS MONIT SYS LATCH CHILD SAFETY SYSTEM PERIMETER ALARM PERSONAL SAFETY SYSTEM™ SOS POST-CRASH ALERT SYS™ WARRANTY 3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST CMMATION \$41,655.00 	Image: Start Star
	RAMP ONE CU41	ΤΟΤΑΙ	. MSRP \$43,650.00	1FMUK8DH9SGB87755
	RAMP TWO	CONVOY 16-K995 O/T 5B Ford Credit	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine explead, which are known to the State of California to cause cance
	This label is affixed pursuant to t Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not in	oline, License, and Title Fees, luded. Dealer installed SE162 R	SPECIAL ORDER RB X 545 000016 05 16 25	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

