СНІ-003750 он	9-NORMAL,NB,103750,RJ091	031 120240916 4958	UTC U W OH   CERT CERT CERT TRD RAMP BUMP	CAMP BOOK EXFL ROTA 025652 353/1573
	ICLE DESCRIPTION EXPLORER ST-LINE 4W 2025 EXPLORER ST-LINE 4W 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISS	RAPID RED N INTERIOR	SG A57260 MET TINTED CC EX SEATS	EPA DOT Fuel Economy and Environ Fuel Economy MPG. The best vehicle of MPG. The best vehicle of
STANDARD EQUIPMENT INCLUDED A EXTERIOR • 'EXPLORER' HOOD BADGING • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • GRILLE - BLACK MESH INSERT • HEAD/TAILLAMPS - BLACKOUT • HEADLAMPS - AUTO LED • LED SIGNATURE LIGHTING • LIFTGATE SCUFF • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • UNIQUE ST-LINE BADGING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR RAPID RED MET TINTED CC 2ND ROW CAPTAIN'S CHAIRS BLUECRUISE EQUIP: 90DAY TRIAL 50 STATE EMISSIONS TWIN PANEL MOONROOF MULTICONTOUR FRONT SEATS PREMIUM PACKAGE .AMBIENT LIGHTING .AUTO-DIMMING REARVIEW MIRROR .110V/150W AC POWER OUTLET ST-LINE STREET PACK .P275/45R21 A/S BSW TIRES .PERFORMANCE BRAKES .21" ALUMINUM WHEELS SEATS - THIRD ROW POWERFOLD	AT NO EXTRA CHARGE INTERNAL PARAMAN AND AND AND AND AND AND AND AND AND A		\$46,515.00	Levent and the compared to other vehicles of similar size and weight. Levent at the risk of rigury in a side impact. Side on the risk of rigury in a side impa
	RAMP ONE CQ06	ΤΟΤΑΙ	. MSRP \$54,035.00	www.safercar.gov or 1-888-327-4236
	RAMP TWO	CONVOY #: 44-Z600 O/T 2	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passenger vehic vehicle can expose you to chemicals including engine exhaust, carb lead, which are known to the State of California to cause cancer and birth d
	State and Local taxes are not	asoline, License, and Title Fees,	RB 2X 535 003750 09 09 24	To minimize exposure, avoid breathing exhaust, do not idle the engine exce vehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

