FD

VEHI					
	EXPLOREF			398149	EPA DOT Fuel Economy and E
Oord	2025 EXPLORER PLATIN 119" WHEELBASE		ERIOR STAR WHITE MET TRI-CO	AT	Fuel Economy
ford.com	3.0L ECOBOOST V6 ENG 10-SPEED AUTO TRANSI		ERIOR MOJAVE DUSK LEATHER	SEATS	MPG. Th
STANDARD EQUIPMENT INCLUDED A	T NO EXTRA CHARGE				
EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • FRT/RR SKID PLATE ELEMENTS • GRILLE - UNIQUE SATIN • HEADLAMPS - ADAPTIVE LED • LED SIGNATURE LIGHTING • MIRRORS-PWR/HTD/AUTO-FOLD SIG/APRCH LAMP/MEM/AUTODIM • PANORAMIC VISTA ROOF® • PRIVACY GLASS - REAR DOORS • ROOF-RACK SIDE RAILS-SATIN	INTERIOR • "EXPLORER" FRNT FLOOR MAT • 110V/150W AC POWER OUTLET • 12.3" LCD DIGITAL CLUSTER • 2ND ROW HEATED SEATS • AMBIENT LIGHTING • AUTO-DIM REARVIEW MIRROR • HTD LTHR WRAPPED STEERING WHEEL W/MOUNTED CONTROL AND TILT/TELE STR COLUMN • HTD/VENTILATED FRT SEATS • LEATHER-WRAPPED INTERIOR	T • B&O SOUND SYSTE • FORD CO-PILOT360 • FORDPASS™ CONN • HILL START ASSIST • INTELL ACCESS W/F G • INTERSECTION ASS LS • REMOTE START SYS • SIDE-WIND STABILI • SIRIUSXM® W/360L	CREEN • ADVANC M, 14 SPKR • AIRBAG ™ACTIVE2.0 • AIRBAG ECT • AIRBAG BUSH START • AIRBAG IST • INDIV TII STEM • LATCH C ZATION • PERIME • NA AK&HI • PERSON	SECURITY DETRAC [™] WITH RSC® - DRIVER KNEE S - DUAL STAGE FRONT S - FRONT SEAT ED SIDE IMPACT S - SAFETY CANOPY® RE PRESS MONIT SYS CHILD SAFETY SYSTEM TER ALARM VAL SAFETY SYSTEM [™] ST-CRASH ALERT SYS [™]	combined city/hwy city highway 4.8 gallons per 100 miles Annual fuel COST \$2,500
• TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • WIPERS - RAIN-SENSING	• POWERFOLD 3RD ROW SEAT • UNIVSL GARAGE DOOR OPENE • USB-C - ALL ROWS	WIRELESS APPLE C AND ANDROID AUTC)™ <u>WARRAN</u> • 3YR/36,0 • 5YR/60,0	TY 000 BUMPER / BUMPER 000 POWERTRAIN 000 ROADSIDE ASSIST	Actual results will vary for many reasons, including driving vehicle. The average new vehicle gets 28 MPG and costs \$5 based on 15,000 miles per year at \$3.50 per gallon. MPGe is emissions are a significant cause of climate change and sm
INCLUDED ON THIS VEHICLE	(MSRP)			(MSRP)	emissions are a significant cause of climate change and sm
EQUIPMENT GROUP 600A			PRICE INFORMATION BASE PRICE	\$52,100.00	fueleconomy.gov
OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR STAR WHITE MET TRI-COAT 3.0L ECOBOOST V6 ENGINE P275/45R21 A/S BSW TIRES BLUECRUISE EQUIP: 1 YEAR PLAN LUX LEATHER PACKAGE 50 STATE EMISSIONS 21" DARK ALLOY ALUM WHLS ULTIMATE PACKAGE MINI SPARE AND JACK KIT FRONT LICENSE PLATE BRACKET DEALER INSTALLED OPTIONS Roadside Assistance Kit Wheel Lock Kit	<text></text>		BASE PHICE TOTAL OPTIONS/OTHER TOTAL VEHICLE & OPTIONS DESTINATION & DELIVERY	5,970.00	Calculate personalized estimates and compare vehicles GOVERNMENT 5-STAR SAFE Overall Vehicle Score Based on the combined ratings of frontal, side and rollove Should ONLY be compared to other vehicles of similar siz Frontal Driver Crash Passenger Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar siz Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Based on the risk of injury in a side impact. Should ONLY be compared to other vehicles of similar siz Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Star ratings range from 1 to 5 stars (* * * * *), Source: National Highway Traffic Safety Adm www.safercar.gov or 1-888-327
	CH7L		TOTAL MSRP	\$59,665.00	1FMWK7HCXSGB9814
	RAMP TWO	CONVOY		lecide to lease or finance your	
		ITEM #: 52-Z301 O/T 2	Ford Credit for you. See yo www.ford.com	find the choices that are right our dealer for details or visit n/finance.	WARNING: Operating, servicing and maintaining a p vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause ca
	Information Disclosure State and Local taxes an	suant to the Federal Automobile Act. Gasoline, License, and Title Fees, re not included. Dealer installed are not included unless listed above.	SD171 N RB 2X 555	002054 04 17 25	To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passe

