СНІ-004630 м	N 9-NORMAL,NB,104630,SD161 154 4	4 120250429 3421	UTCUWMNCERTCERTCERTTRDRAMPCERTCERTTRDRAMPBUMP	AMP BOOK EXFL ROTA 02 1178/
ford.com	VEHICLE DESCRIPTION EXPLORER PLATINUM 4WD 119" WHEELBASE 3.0L ECOBOOST V6 ENGINE 10-SPEED AUTO TRANSMISSION ED AT NO EXTRA CHARGE	STAR WHITE INTERIOR	SG CO1498 Met tri-coat Ray leather seats	EPA DOT Fuel Economy and Env Fuel Economy MPG. The be
EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • FRT/RR SKID PLATE ELEMENTS • GRILLE - UNIQUE SATIN • HEADLAMPS - ADAPTIVE LED • LED SIGNATURE LIGHTING • MIRRORS-PWR/HTD/AUTO-FOLE SIG/APRCH LAMP/MEM/AUTODIN • PANORAMIC VISTA ROOF® • PRIVACY GLASS - REAR DOORS • ROOF-RACK SIDE RAILS-SATIN • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 600A OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR STAR WHITE MET TRI-COAT 3.0L ECOBOOST V6 ENGINE P275/45R21 A/S BSW TIRES BLUECRUISE EQUIP: 1 YEAR PLAN LUX LEATHER PACKAGE 50 STATE EMISSIONS 21" DARK ALLOY ALUM WHLS ULTIMATE PACKAGE INFLATOR KIT-DELETE SPARE TIRE FRONT LICENSE PLATE BRACKET	 INTERIOR "EXPLORER" FRNT FLOOR MATS 110V/150W AC POWER OUTLET 12.3" LCD DIGITAL CLUSTER 20.4 AMBIENT LIGHTING AUTO-DIM REARVIEW MIRROR HTD LTHR WRAPPED STEERING WHEEL W/MOUNTED CONTROLS AND TILT/TELE STR COLUMN HTD/VENTILATED FRT SEATS LEATHER-WRAPPED INTERIOR POWERFOLD 3RD ROW SEAT UNIVSL GARAGE DOOR OPENER USB-C - ALL ROWS 795.00 NO CHARGE NO CHARGE NO CHARGE AG15.00	TOTAL VEHI	WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST (MSRP) DRMATION	Image: Angle and a generative of the second sec
	ITEM #:	CONVOY B-X519 O/T 2 Federal Automobile ne, License, and Title Fees,	L MSRP \$61,105.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	IFMWK8HCOSGC01498 WARNING: Operating, servicing and maintaining a passer vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the ex- vehicle in a well-ventilated area and wear gloves or wash your has

SD161 N RB 2X 555 004630 04 16 25

State and Local taxes are not included. Dealer installed

options or accessories are not included unless listed above.

1202504293421

