



ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2025 F250 SRW 4X4 CREW CAB
XL 160" WB STYLESIDE
6.8L DEVCT NA PFI V8 ENGINE
10-SPEED AUTO TORQSHIFT-G

SE

E02286

EXTERIOR
CARBONIZED GRAY

INTERIOR
MEDIUM DARK SLATE CLOTH

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- DOOR HANDLES - BLACK
- HEADLAMPS - AUTOLAMP (ON/OFF)
- TOW HOOKS
- TRAILER SWAY CONTROL
- TRAILER TOW MIRRORS
- WIPERS- INTERMITTENT

INTERIOR

- 4.2" PRODUCTIVITY SCREEN
- AIR COND, MANUAL FRONT
- CLOTH SUN VISORS
- DRIVER SEAT-MANUAL LUMBAR
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS

FUNCTIONAL

- 4-WHEEL ANTILOCK BRAKE SYS
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- HILL START ASSIST
- MANUAL LOCKING HUBS
- MONO BEAM COIL SPRING FRT SUSPENSION W/STAB BAR
- REAR VIEW CAMERA
- REMOTE KEYLESS ENTRY
- SYNC®4 W/8" SCREEN

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SECURE PKG 1 YR INCLUDED
- SECURILOCK® ANTI-THEFT SYS
- SOS POST-CRASH ALERT SYST™

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.600A

10-SPEED AUTO TORQSHIFT-G

3.73 ELECTRONIC-LOCKING AXLE

FRONT LICENSE PLATE BRACKET

10000# GVWR PACKAGE

50 STATE EMISSIONS

BACKGLASS DEFROST

120V/400W OUTLET

POWER SLIDING REAR WINDOW

SNOW PLOW PREP PACKAGE

SPARE TIRE AND WHEEL

TRAILER BRAKE CONTROLLER

ROOF CLEARANCE LIGHTS

JACK

UPFITTER SWITCHES

250 AMP ALTERNATOR

CLOTH 40/20/40 SEAT

PRIVACY GLASS

XL DRIVER ASSIST PACKAGE

XL CHROME PACKAGE

.FOG LAMPS

(MSRP)

NO CHARGE

430.00

NO CHARGE

NO CHARGE

175.00

405.00

250.00

NO CHARGE

300.00

95.00

230.00

85.00

315.00

100.00

730.00

325.00

PRICE INFORMATION

BASE PRICE

\$51,890.00

TOTAL OPTIONS/OTHER

3,440.00

TOTAL VEHICLE & OPTIONS/OTHER

55,330.00

DESTINATION & DELIVERY

2,095.00

(MSRP)

RAMP ONE

RC73

RAMP TWO

RAIL


ITEM #:

41-2002 O/T 2

TOTAL MSRP

\$57,425.00

Scan The QR Code to
get more details about
this vehicle



This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

SF103 N RB 2X 530 003146 06 10 25

California Air Resources Board

Gasoline Vehicle

Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings. For information on how to compare, please see www.arb.ca.gov/ep_label.

Protect the environment. Choose vehicles with higher ratings:

Greenhouse Gas Rating (tailpipe only)

A+

Cleaner

D

D

Smog Rating (tailpipe only)


A+

Cleaner

A-

D

Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.



GOVERNMENT 5-STAR SAFETY RATINGS

Overall Vehicle Score

Not Rated

Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size and weight.

Frontal Crash

Driver Passenger

Not Rated

Not Rated

Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and weight.

Side Crash

Front seat

Rear seat

Not Rated

Not Rated

Based on the risk of injury in a side impact.


Rollover

Not Rated

Based on the risk of rollover in a single-vehicle crash.

Star ratings range from 1 to 5 stars (★★★★★), with 5 being the highest. Source: National Highway Traffic Safety Administration (NHTSA). www.safercar.gov or 1-888-327-4236

1FT7W2BA8SEE02286



WARNING:

Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

Credit

Get Prequalified now at www.ford.com/finance