VEHICLE DESCRIPTION SE D40565 JOINT DESCRIPTION See D40565 <	comparable to ow to compa ment. Cho g (tailpipe only
STANDARD EQUIPMENT INCLODED AT NO EXTRA CHARGE STANDARD EQUIPMENT INCLODED AT NO EXTRA CHARGE STANDARD EQUIPMENT INCLODED AT NO EXTRA CHARGE EXTERIOR • FOG LAMPS • FOG LAMPS • HEADLAMPS - AUTO HIGH BEAM • AIR COND, MANUAL FRONT • HILL START ASSIST • ON/OFF) • CLOTH SUN VISORS For information on herein the start assist in the start assist	ow to compa ment. Cho g (tailpipe only
EXTERIORINTERIORFUNCTIONALSAFETY/SECURITY• FOG LAMPS• 120V OUTLET• FORDPASS™ CONNECT 5GWI-FI• ADVANCETRAC™ WITH RSC®• HEADLAMPS - AUTO HIGH BEAM• 1TOUCH UP/DOWN DR/PASS WIN• HOTSPOT TELEMATICS MODEM• AIRBAGS - SAFETY CANOPY®• HEADLAMPS - AUTOLAMP• AIR COND, MANUAL FRONT• HILL START ASSIST• BELT-MINDER CHIME• (ON/OFF)• CLOTH SUN VISORS• MONO BEAM COIL SPRING FRT• DRIVER/PASSENGER AIR BAGS	ment. Cha
 • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER BRAKE CONTROL • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • CLTH SEATS W/8-WAY PWR DRV • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS • UPPER GLOVEBOX STORAGE • STORAGE • SUSPENSION W/STAB BAR • PRE-COLLISION ASSIST W/AEB • PRE-COLLISION ASSIST W/AEB • PRE-COLLISION ASSIST W/AEB • SOS POST-CRASH ALERT SYS™ • SON BUMPER / BUMPER • SYR/60,000 BUMPER / BUMPER • SYR/60,000 POWERTRAIN • SYR/60,000 DIESEL ENGINE 	D
INCLUDED ON THIS VEHICLE (MSRP) Vehicle emissions are a primary contribution OPTIONAL EQUIPMENT/OTHER (MSRP) PRICE INFORMATION California Air Resources Board based 4014-716S01/01/24 BP994Y BASE PRICE \$55,905.00 10,445.00 PREFERRED EQUIPMENT PKG.603A 10,495.00 10,495.00 10,495.00 10-SPEED AUTO TOROSHIESEL 10,495.00 NO CHARGE TOTAL VEHICLE & OPTIONS/OTHER 66,350.00	
10-SPEED AUTO TORQSHIFT NO CHARGE IOTAL VEHICLE & OPTIONS/OTHER 66,350.00 L1275/65R18E BSW ALL SEASON 0.31 RATIO NON LTD SLIP AXLE NO CHARGE 1,995.00 RONT LICENSE PLATE BRACKET NO CHARGE NO CHARGE 0.0000/0000/0000/0000/0000/0000/0000/0	Not Rate e and rollover. of similar size and Not Rate Not Rate
Side Front seat Crash Rear seat Based on the risk of injury in a side impact.	Not Rate Not Rate
Rollover Based on the risk of rollover in a single-vehicle Star ratings range from 1 to 5 stars (* Source: National Highway Traffic S www.safercar.gov or	★★★★), with afety Administ
RAMP ONE RA5B TOTAL MSRP \$68,345.00	ED40565
RAMP TWO RAIL ITEM #: 52-C91F O/T 5C 52-C91F O/T 5C Ford Credit Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. WARNING: Operating, servicing and ma vehicle can expose you to chemicals inclusion	luding engine exha
This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above. SEO61 N RB 2X 515 001933 05 06 25	, do not idle the er s or wash vour ha

