


	<div>RAMP ONE</div> <div>RA26</div>		<div>TOTAL MSRP</div> <div>\$94,150.00</div>
	<div>RAMP TWO</div> <div>ITEM #:</div> <div>56-M028 O/T 2</div>	<div>RAIL</div>	<div>  <div>Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit <a href="http://www.ford.com/finance">www.ford.com/finance</a>.</div> </div>
	<div>This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.</div>		<div>SA081 N RB 2X 520 000665 01 08 25</div>



# California Air Resources Board

## Diesel Vehicle

## Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings.  
For information on how to compare, please see [www.arb.ca.gov/ep\\_label](http://www.arb.ca.gov/ep_label).

Protect the environment. Choose vehicles with **higher ratings**:



Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.



**The FordPass™ Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.\*\* See in-vehicle settings for connectivity options.**

**\*Based on 1977–2023 CY total sales.**  
**\*\*FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes Wi-Fi hotspot.**

1FT8W2BM5SEC16610



**WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, van or vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to [www.P65Warnings.ca.gov/passenger-vehicle](http://www.P65Warnings.ca.gov/passenger-vehicle).

rates may  
apply.  
Text HELP  
for help



[www.ford.com/help/privacy-terms/](http://www.ford.com/help/privacy-terms/)