KIP-UU4I42 TX 9-NORMAL, NB, 104142, RL271 3742			CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA 658	
	CLE DESCRIPTION SUPER DUTY 2025 F250 SRW 4X4 CREW CAB KING RANCH 160" WB STYLESII 6.7 HI OUTPUT POWER STROKE 10-SPEED AUTO TORQSHIFT	3 EXTERIOR D STAR WHITE	SE C04510	California Air Resources Boar Environmer
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • LED FOG LAMPS • LED REFLECTOR HEADLAMPS • PICKUP BOX, TIE DOWN HOOKS • POWER SLIDING REAR WINDOW W/DEFROST & PRIVACY TINT • POWER TAILGATE • POWERSCOPE TT POWER-FOLD MIRRORS, POWER/HEATED • TAILGATE STEP • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER 2025 MODEL YEAR STAR WHITE PREFERRED EQUIPMENT PKG.700A 6.7 HI OUTPUT POWER STROKE 10-SPEED AUTO TORQSHIFT 3.31 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET CHROME PACKAGE .CHROME PVD ALUMINUM WHEELS-20 FX4 OFF-ROAD PACKAGE SKID PLATES POWER RUNNING BOARDS 11100# GVWR PACKAGE ENGINE BLOCK HEATER 50 STATE EMISSIONS PRO POWER ONBOARD - 2KW HIGH CAPACITY TRAILER TOW PKG JACK MOONROOF POWER-TWIN PANEL UPFITTER SWITCHES	Internet Intern		 BELT-MINDER CHIME DRIVER/PASSENGER AIR BAGS LED CTR HIGH MNT STOP LAMP SECURE PKG 1 YR INCLUDED SOS POST-CRASH ALERT SYS™ WARRANTY 3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 DIESEL ENGINE (MSRP) PRMATION \$76,975.00	
	RAMP ONE RK34 RAMP TWO	RAIL	MSRP \$97,960.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	IFT8W2BM7SEC04510 WARNING: Operating, servicing and maintaining a part vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause cancelead.
	This label is affixed pursuant to the Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inc	line, License, and Title Fees, uded. Dealer installed RL271 N	RB 2X 520 004142 11 27 24	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

