



ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2025 F350 SRW 4X4 CREW CAB
XL 176" WB STYLESIDE
6.7L POWER STROKE V8 DIESEL
10-SPEED AUTO TORQSHIFT

SE D78887

EXTERIOR
OXFORD WHITE
INTERIOR
MEDIUM DARK SLATE CLOTH

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- DOOR HANDLES - BLACK
- HEADLAMPS - AUTOLAMP (ON/OFF)
- TOW HOOKS
- TRAILER SWAY CONTROL
- TRAILER TOW MIRRORS
- WIPERS- INTERMITTENT

INTERIOR

- 4.2" PRODUCTIVITY SCREEN
- AIR COND, MANUAL FRONT
- CLOTH SUN VISORS
- DRIVER SEAT-MANUAL LUMBAR
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS

FUNCTIONAL

- 4-WHEEL ANTILOCK BRAKE SYS
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- HILL START ASSIST
- MANUAL LOCKING HUBS
- MONO BEAM COIL SPRING FRT SUSPENSION W/STAB BAR
- REAR VIEW CAMERA
- REMOTE KEYLESS ENTRY
- SYNC®4 W/8" SCREEN

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SECURE PKG 1 YR INCLUDED
- SECURILOCK® ANTI-THEFT SYS
- SOS POST-CRASH ALERT SYST™

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.610A

6.7L POWER STROKE V8 DIESEL

10-SPEED AUTO TORQSHIFT

3.55 ELECTRONIC-LOCKING AXLE

FRONT LICENSE PLATE BRACKET

PLATFORM RUNNING BOARDS

11499# GVWR PACKAGE

50 STATE EMISSIONS

SNOW PLOW PREP PACKAGE

.RAPID HEAT SUPPLEMENTAL HEATE

TRAILER BRAKE CONTROLLER

5TH WHEEL HITCH PREP PACKAGE

ROOF CLEARANCE LIGHTS

JACK

UPFITTER SWITCHES

410 AMP DUAL ALTERNATOR

TAILGATE STEP

DUAL BATTERY

CLOTH 40/20/40 SEAT

XL CHROME PACKAGE

.FOG LAMPS

(MSRP)

10,495.00

NO CHARGE

430.00

NO CHARGE

445.00

NO CHARGE

250.00

300.00

650.00

95.00

230.00

NO CHARGE

375.00

NO CHARGE

315.00

325.00

PRICE INFORMATION

BASE PRICE

\$53,395.00

TOTAL OPTIONS/OTHER

13,910.00


TOTAL VEHICLE & OPTIONS/OTHER

67,305.00

DESTINATION & DELIVERY

2,095.00

(MSRP)

	RAMP ONE		TOTAL MSRP \$69,400.00
	RA26	RAIL	
	RAMP TWO	ITEM #: 56-R557 O/T 2	<div><div></div><div>Ford Credit</div><div>Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.</div></div>
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		
			SE221 N RB 2X 530 002845 05 22 25

California Air Resources Board

Diesel Vehicle

Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings. For information on how to compare, please see www.arb.ca.gov/ep_label.

Protect the environment. Choose vehicles with higher ratings:

Greenhouse Gas Rating (tailpipe only)

A+

C-

D

Cleaner

Smog Rating (tailpipe only)

A+

B

D

Cleaner

Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.



48 YEARS BUILT Ford TOUGH

F-SERIES®

AMERICA'S BEST SELLING TRUCKS

The FordPass™ Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.** See in-vehicle settings for connectivity options.

*Based on 1977–2024 CY total sales.

**FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes WI-FI hotspot.

1FT8W3BT6SED78887





WARNING:

Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

rates may apply. Text HELP for help



www.ford.com/help/privacy-terms/