KTP-000325 PA	44D 026 6B 2 X LABL ADJ COV PRCS	B10 RAMP BUMP	8X3BA3REE61229	SUPER	MAIL	02 531
	ICLE DESCRIPTION SUPER DUT 2024 F350 SRW 4X4 SUPERCA XL 164" WB STYLESIDE 6.8L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT-(AB EXTERIO OXFO E INTERIO	DR DRD WHITE	61229	California Air R En	esources Board vironmen
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.610A 10-SPEED AUTO TORQSHIFT-G FRONT LICENSE PLATE BRACKET XL OFF-ROAD LT285/70R17 AT .3.73 ELECTRONIC-LOCKING AXLE .SKID PLATES PLATFORM RUNNING BOARDS 10800# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SNOW PLOW PREP PACKAGE 51 OSTATE EMISSIONS 120V/400W OUTLET SNOW PLOW PREP PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SNOW PLOW PREP PACKAGE 50 GLAMPS		EUNCTIONAL • 4-WHEEL ANTILOCK BRA • FORDPASS™ CONNECT HOTSPOT TELEMATICS M • HILL START ASSIST • MANUAL LOCKING HUBS • MONO BEAM COIL SPRIN SUSPENSION W/STAB BA • REAR VIEW CAMERA • REMOTE KEYLESS ENTR • SYNC®4 W/8" SCREEN PE BA TO	SAFETY/SEC KE SYS • ADVANCETF 5GWI-FI • AIRBAGS - S MODEM • BELT-MINDE • DRIVER/PAS • SECURILOC IG FRT • SOS POST-C R <u>WARRANTY</u> Y • 3YR/36,000 I • 5YR/60,000 I	URITY RAC™ WITH RSC® SAFETY CANOPY® ER CHIME ISENGER AIR BAGS K® ANTI-THEFT SYS CRASH ALERT SYS™ BUMPER / BUMPER POWERTRAIN ROADSIDE ASSIST DIESEL ENGINE (MSRP) \$51,345.00 2,580.00	For inform	Using alternative
	RAMP ONE RB2M RAMP TWO ITEM #: This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not im options or accessories are not im	RAIL 44-1142 O/T 59 the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed	Whether you decid	RDER	WARNING: Operating, se vehicle can expose you to lead, which are known to the Sta To minimize exposure, avoid bre vehicle in a well-ventilated area For more information go to www	1FT8X3BA3REE61229 ervicing and maintaining a pass o chemicals including engine end ate of California to cause cance eathing exhaust, do not idle the and wear gloves or wash your v.P65Warnings.ca.gov/passeng

