KTP-002805 KS	9-NORMAL,NB,302805,SF103	17946	CERTCERTCER'	T TRD RAMPBUMPCAME	PBOOKEXFLROTABATT	2444/3
	SUPER DU	ΓY	SE D	95279	California Air Res	ources Board
ford.com	2025 F250 SRW 4X2 REG ( XL 142" WB STYLESIDE 6.8L DEVCT NA PFI V8 ENG 10-SPEED AUTO TORQSHI	CAB EXTERIO OXFO GINE INTERIO			These ratings are not o	
EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT	INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • CLOTH SUN VISORS • DRIVER SEAT-MANUAL LUMBAR • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS	EUNCTIONAL • 4-WHEEL ANTILOCK BRA • FORDPASS™ CONNECT HOTSPOT TELEMATICS M • HILL START ASSIST • REAR VIEW CAMERA • REMOTE KEYLESS ENTR • SYNC®4 W/8" SCREEN • TWIN I-BEAM INDEPEND FRT SUSPENSION W/STA	5GWI-FI MODEM * BELT-MINDE * DRIVER/PAS * SECURE PK * SECURE PK * SECURILOC * SOS POST-C ENT * BBAR * WARRANTY * 3YR/36,000 I * 5YR/100,000	RAC™ WITH RSC® SAFETY CANOPY®		D
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.600A 10-SPEED AUTO TORQSHIFT-G LT245/75R17E BSW ALL-TERRAIN 3/3 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS 1000# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SPARE TIRE AND WHEEL TRAILER BRAKE CONTROLLER INTERIOR WORK SURFACE ROOF CLEARANCE LIGHTS JACK UPFITTER SWITCHES 250 AMP ALTERNATOR XL DRIVER ASSIST PACKAGE .FOG LAMPS	(MSRP) NO CHARGE 165.00 430.00 NO CHARGE 320.00 NO CHARGE 175.00 NO CHARGE 300.00 140.00 95.00 230.00 85.00 730.00 325.00	B/ TC TC	RICE INFORMATION ASE PRICE DTAL OPTIONS/OTHER DTAL VEHICLE & OPTIONS/OTH ESTINATION & DELIVERY	(MSRP) \$45,300.00 2,995.00 HER 48,295.00 2,095.00	California Air Resources Boar GOVERNMENT Overall Vehicle Score Based on the combined ratings of Should ONLY be compared to othe Frontal Driver Crash Passen Based on the risk of injury in a from Should ONLY be compared to othe Side Front set Crash Rear set Based on the risk of injury in a side Rollover Based on the risk of rollover in a side Star ratings range from 1 to 5 side Source: National Highway	<b>5-STAR SAFETY R</b> <b>Not Rate</b> frontal, side and rollover. er vehicles of similar size and <b>Not Rate</b> <b>Not Rate <b>Rate</b> <b>Not Rate</b> <b>Not Rate <b>Rate</b> <b>Not Rate</b></b></b>
	RAMP ONE CM6P RAMP TWO	CONVOY S	OTAL MSRP	VID 4523164	1FT WARNING: Operating, service vehicle can expose you to chu lead, which are known to the State of	BF2AA2SED95279
	Information Disclosure Act State and Local taxes are r	ant to the Federal Automobile t. Gasoline, License, and Title Fees,	SF103 N RB 2X 530 002	805 06 10 25	To minimize exposure, avoid breathing vehicle in a well-ventilated area and For more information go to www.P65	ng exhaust, do not idle the en wear gloves or wash your hai

