KTP-002186 CA	9-NORMAL, NB, 102186, SD301 4940	0	CERTCERTCERT TRD F	RAMPBUMPCAMI	PBOOKEXFLROTABA	TT	029 1615/1
	SUPER DUTY	,	^{se} D64	843	California	Air Resourc	es Board
ford.com		INTERIOF MEDIL	RD WHITE IM DARK SLATE VINYL			Enviror as are not directly r information on h	comparable to
EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT	INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • CLOTH SUN VISORS • DRIVER SEAT-MANUAL LUMBAR • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS	EUNCTIONAL • 4-WHEEL ANTILOCK BRAH • FORDPASS™ CONNECT 5 HOTSPOT TELEMATICS MO • HILL START ASSIST • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • SYNC®4 W/8" SCREEN • TWIN I-BEAM INDEPENDE FRT SUSPENSION W/STAE	GWI-FI DDEM • BELT-MINDER CHIM • DRIVER/PASSENGEF • SECURE PKG 1 YR II • SECURILOCK® ANTI • SOS POST-CRASH A	CANOPY® IE R AIR BAGS NCLUDED I-THEFT SYS ILERT SYS™ R / BUMPER ENGINE FRAIN	Greenhous A+ Cleaner	et the environ se Gas Ratin	g (tailpipe onl
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.600A 10-SPEED AUTO TORQSHIFT-G 3.73 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET 10000# GVWR PACKAGE 50 STATE EMISSIONS SPARE TIRE AND WHEEL TRAILER BRAKE CONTROLLER JACK UPFITTER SWITCHES 250 AMP ALTERNATOR XL CHROME PACKAGE .FOG LAMPS	(MSRP) NO CHARGE 430.00 NO CHARGE NO CHARGE 300.00 230.00 85.00 325.00	BAS TOT TOT	CE INFORMATION SE PRICE TAL OPTIONS/OTHER TAL VEHICLE & OPTIONS/OTHER STINATION & DELIVERY	(MSRP) \$45,300.00 1,370.00 46,670.00 2,095.00	California Air Reso GOVER Overall Vehic Based on the combi Should ONLY be con Frontal Crash Based on the risk of Should ONLY be con Side Crash Based on the risk of Rollover Based on the risk of Star ratings range	ned ratings of frontal, sid mpared to other vehicles Driver Passenger injury in a frontal impact. Front seat Rear seat injury in a side impact. rollover in a single-vehic from 1 to 5 stars (★	on this vehicle R SAFETY F Not Rate le and rollover. of similar size and Not Rate Not Rate Not Rate Not Rate Not Rate Not Rate Soft and the size and Not Rate Not Rate Not Rate
	RAMP ONE RA84 RA84 RAMP TWO ITEM #: 72 This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not includ options or accessories are not included options optio	RAIL 2-8027 O/T 2 Federal Automobile ne, License, and Title Fees, led. Dealer installed	OTAL MSRP \$48,7 Image: Second conductive state of the second conductive sta	es that are right details or visit	WARNING: Op vehicle can exp lead, which are known To minimize exposure vehicle in a well-ventil	nal Highway Traffic S www.safercar.gov o 1FTBF2AA4S rerating, servicing and ma bose you to chemicals inco to the State of California , avoid breathing exhaust ated area and wear glove go to www.P65Warnings.	r 1-888-327-423 SED64843 intaining a passer cluding engine exh a to cause cancer a t, do not idle the er es or wash your ha

