KTP-003420 SC 9-NORMAL,	NB,103420,SB111 855	6		FRTCERTCERT TRD F	AMP BUMP C	AMP BOOK EXFL RC	DTA	028 3053/3
VEHICLE DESCRIPT		,		se C881	29	California	Air Resource	es Board
XL 142 6.8L D	5250 SRW 4X2 REG CAB 2" WB STYLESIDE EVCT NA PFI V8 ENGINE EED AUTO TORQSHIFT-G		ERIOR DXFORD WHITE ERIOR MEDIUM DARK				Enviror	nment
STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE						These ratings are not directly comparable to For information on how to compar		
HEADLAMPS - AUTOLAMP ON/OFF) ON/OFF) CLOTH SI	DUCTIVITY SCREEN D, MANUAL FRONT UN VISORS BEAT-MANUAL LUMBAR	EUNCTIONAL • 4-WHEEL ANTILOCK • FORDPASS™ CONN HOTSPOT TELEMATI • HILL START ASSIST	ECT 5GWI-FI	SAFETY/SECURITY • ADVANCETRAC™ WITH • AIRBAGS - SAFETY CAN • BELT-MINDER CHIME • DRIVER/PASSENGER A	NOPY®	Prote	ct the environ	ment. Cho
• TRAILER SWAY CONTROL • OUTSIDE • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT • POWER L • STEERING	TEMP DISPLAY LATE AIR FILTER LOCKS AND WINDOWS G:TILT/TELESCOPE,	REAR VIEW CAMERA REMOTE KEYLESS EI SYNC®4 W/8" SCREE TWIN I-BEAM INDEPE	A ENTRY EN PENDENT	SECURE PKG 1 YR INCLUDED SECURILOCK® ANTI-THEFT SYS SOS POST-CRASH ALERT SYS™		Greenhouse Gas Rating (tailpipe only		
	AUDIO CONTROLS	FRT SUSPENSION W	FRT SUSPENSION W/STAB BAR		WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/100,000 DIESEL ENGINE • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST		A+ Cleaner	
INCLUDED ON THIS VEHICLE (MSRP)					(MSRP)		ns are a primary contr sources Board based	
OPTIONAL EQUIPMENT/OTHERPREFERRED EQUIPMENT PKG.600A10-SPEED AUTO TORQSHIFT-G3.73 ELECTRONIC-LOCKING AXLE430.00			PRICE INFORM BASE PRICE TOTAL OPTION	S/OTHER	\$45,300.00 1,725.00			
10000# GVWR PACKAGE50 STATE EMISSIONSNO CHARGE120V/400W OUTLET175.00SPARE TIRE AND WHEELNO CHARGEINTERIOR WORK SURFACE140.00JACK140.00	TOTAL VEHICLE DESTINATION &			& OPTIONS/OTHER 47,025.00 DELIVERY 1,995.00				
UPFITTER SWITCHES 165.00 250 AMP ALTERNATOR 85.00 XL DRIVER ASSIST PACKAGE 730.00						Frontal Crash Based on the risk of Should ONLY be c	Driver Passenger of injury in a frontal impact. ompared to other vehicles	Not Rate Not Rate
						Side Crash	Front seat Rear seat of injury in a side impact.	Not Rate Not Rate
						Rollover Based on the risk o	of rollover in a single-vehicl	Not Rate
						Star ratings rang	e from 1 to 5 stars (★ onal Highway Traffic S www.safercar.gov or	★★★★), with Safety Administ
	RAMP ONE						1FTBF2AA7S	
	RAMP TWO	RAIL 1-3762 O/T 2	Ford Credit fo	hether you decide to lease or hicle, you'll find the choices r you. See your dealer for det ww.ford.com/finance.	that are right	WARNING: C vehicle can ex	Operating, servicing and ma xpose you to chemicals inc vn to the State of California	aintaining a passen luding engine exha
	This label is affixed pursuant to the Information Disclosure Act. Gasoliu State and Local taxes are not incluc options or accessories are not incl	ne, License, and Title Fees, ded. Dealer installed	SB111 N R	3 2X 520 003420 02 11	25	To minimize exposur vehicle in a well-ven	re, avoid breathing exhaust tilated area and wear glove n go to www.P65Warnings.	, do not idle the er s or wash vour ha

