
	ICLE DESCRIPTION		^{sк} А836	54	California Air Resou	rces Board
Ford.com	2025 250 HR CARGO RWD 148" WHEELBASE 3.5L ECOBOOST V6 (GAS) 10-SPEED TRANSMISSION	INTERIOR	EXTERIOR OXFORD WHITE		Environment	
STANDARD EQUIPMENT INCLUDED A	AT NO EXTRA CHARGE				These ratings are not direc For information o	, ,
EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • HEADLAMP COURTESY DELAY • WIPERS - RAIN-SENSING	INTERIOR • AIR CONDITIONING • ASSIST HANDLES - A-PILLAR • CENTER CONSOLE • INTERIOR LIGHTING - LED • LOCKING GLOVE BOX • POWERPOINT - 12V (FRONT) • STEERING - TILT/TELESCOPIC • TACHOMETER	FUNCTIONAL • AUTO HIGH-BEAM HEADLAMPS • ELECTRONIC PWR ASST STEER • FORWARD COLLISION WARNING • HILL START ASSIST • LANE-KEEPING SYSTEM • POST-COLLISION BRAKING • PRE-COLLISION ASSIST W/AEB • REAR VIEW CAMERA W/ TRAILER HITCH ASSIST • SELECTABLE DRIVE MODES • SIDE-WIND STABILIZATION	SAFETY/SECURITY • 3 POINT SAFETY BELTS • ADVANCETRAC [™] WITH F • AIRBAGS ⊠ FRONT, SIDE SAFETY CANOPY® SYSTI • BRAKES - 4WHEEL DISC • SECURILOCK® ANTI-THE • SOS POST-CRASH ALER • TIRE PRESSURE MONITS WARRANTY • 3YR/36,000 BUMPER / BU • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE AS	AND EM W/ABS FT SYS T SYS™ SYS JMPER	Protect the environ Greenhouse Gas Rat A+ Cleaner	
INCLUDED ON THIS VEHICLE	(MSRP)			(MSRP)	Vehicle emissions are a primary co California Air Resources Board bas	
OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.101A 3.5L ECOBOOST V6 (GAS) 3.73 NON-LIMITED SLIP AXLE REAR COMPARTMENT LIGHTING FRONT LICENSE PLATE BRACKET 9150# GVWR PACKAGE 50 STATE EMISSIONS BACK UP ALARM D-PILLAR ASSIST HANDLES 2 ADDITIONAL KEYS	2,700.00 NO CHARGE 75.00 NO CHARGE NO CHARGE 185.00 60.00 75.00	PRICE INFOR BASE PRICE TOTAL OPTION TOTAL VEHICL DESTINATION	NS/OTHER	\$51,800.00 3,095.00 54,895.00 2,095.00	GOVERNMENT 5-S Overall Vehicle Score Based on the combined ratings of frontal Should ONLY be compared to other vehi Frontal Driver Crash Passenger Based on the risk of injury in a frontal im Should ONLY be compared to other vehi Side Front seat Crash Rear seat Based on the risk of injury in a side impa Real con the risk of injury in a side impa Based on the risk of injury in a side impa Based on the risk of rollover in a single-v Star ratings range from 1 to 5 stars Source: National Highway Traff	Not Rate , side and rollover. cles of similar size and
	RAMP ONE	TOTAL	MSRP \$56,99	0.00		ov or 1-888-327-423 (G0SKA83654
	CM32		e QR Code to			
	RAMP TWO		e details about		WARNING: Operating, servicing an vehicle can expose you to chemical	d maintaining a passen s including engine exha
This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.			SPECIAL ORDER SF042 N RB 2X 530 002698 06 04 25		lead, which are known to the State of Calif To minimize exposure, avoid breathing exh vehicle in a well-ventilated area and wear For more information go to www.P65Warn	aust, do not idle the en

1202506122902



ated ated

ated

ith 5 being the highest. istration (NHTSA). 236



senger vehicle, pickup truck, v exhaust, carbon monoxide, phtl er and birth defects or other reproductive narm. engine except as necessary, service your hands frequently when servicing your vehicle. ger-vehicle

Credit Get Prequalified now at www.ford.com/finance

• Connect up to ten Wi-Fi–equipped devices.

*Compatible with select smartphone platforms. FordPass ConnectTM service required (see App Terms for more information). Connected service and related feature functionality's subject to compatible ATG T-instruction selection service into an experimental service in the service of the service and the availability, or continued provision of some features, pohibiting them from functioning. Message and data rates may apply Sides your load Ford website for our privacy policy.

The FordPass Connect™ modem is active and sending vehicle data (e.g., diagnostics) to Ford. See

in-vehicle Settings for connectivity options.

