



ford.com

VEHICLE DESCRIPTION

TRANSIT

2025 250 HR CARGO RWD  
148" WHEELBASE  
3.5L PFDI V6 (GAS)  
10-SPEED TRANSMISSION

EXTERIOR  
OXFORD WHITE

INTERIOR  
DARK PALAZZO GRAY CLOTH

SK A07641

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- AUXILIARY FUEL PORT
- BODY SIDE MOLDINGS - BLACK
- BUMPERS - CARBON BLACK
- FULL SIZE SPARE TIRE/WHEEL
- HEADLAMP COURTESY DELAY
- WIPERS - RAIN-SENSING

INTERIOR

- AIR CONDITIONING
- ASSIST HANDLES - A-PILLAR
- CENTER CONSOLE
- INTERIOR LIGHTING - LED
- LOCKING GLOVE BOX
- POWERPOINT - 12V (FRONT)
- STEERING - TILT/TELESCOPIC
- TACHOMETER

FUNCTIONAL

- AUTO HIGH-BEAM HEADLAMPS
- ELECTRONIC PWR ASST STEER
- FORWARD COLLISION WARNING
- HILL START ASSIST
- LANE-KEEPING SYSTEM
- POST-COLLISION BRAKING
- PRE-COLLISION ASSIST W/AEB
- REAR VIEW CAMERA
- W/ TRAILER HITCH ASSIST
- SELECTABLE DRIVE MODES
- SIDE-WIND STABILIZATION

SAFETY/SECURITY

- 3 POINT SAFETY BELTS
- ADVANCETRAC™ WITH RSC®
- AIRBAGS  FRONT, SIDE AND SAFETY CANOPY® SYSTEM
- BRAKES - 4WHEEL DISC W/ABS
- SECURILOCK® ANTI-THEFT SYS
- SOS POST-CRASH ALERT SYSTM™
- TIRE PRESSURE MONIT SYS

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.101A

4.10 LIMITED SLIP AXLE

FRONT LICENSE PLATE BRACKET

9150# GVWR PACKAGE

2WAY DRV/PASS PALAZZO CLOTH

B-PILLAR ASSIST HANDLE

50 STATE EMISSIONS

BACK UP ALARM

REVERSE SENSING SYSTEM

FRONT FOG LAMPS

ELEC AIR TEMP CONTROL

SYNC 4 HD BLUETOOTH

360-DEGREE CAMERA

D-PILLAR ASSIST HANDLES

FRONT OVERHEAD SHELF

2 ADDITIONAL KEYS

WIPER ACTIVATED HEADLAMPS

BLACK HID HEADLAMPS

LOAD AREA PROTECTION PKG

.VINYL F/R FLOOR COVERING

E-85 FLEX FUEL CAPABLE

(MSRP)

NO CHARGE

NO CHARGE

NO CHARGE

115.00

25.00

NO CHARGE

185.00

NO CHARGE

NO CHARGE

NO CHARGE

1,165.00

1,000.00

60.00

75.00

75.00

30.00

455.00

575.00

NO CHARGE

PRICE INFORMATION

BASE PRICE

5\$3,000.00

TOTAL OPTIONS/OTHER

3,760.00

TOTAL VEHICLE & OPTIONS/OTHER

56,760.00

DESTINATION & DELIVERY

2,095.00

	RAMP ONE		TOTAL MSRP \$58,855.00
	CM7L	CONVOY	
	RAMP TWO	ITEM #:	SA221 N RB 2X 520 007191 01 22 25
		52-T108 O/T 2	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		

California Air Resources Board

Flexible-Fuel Vehicle Gasoline-Ethanol (E85)

Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings. For information on how to compare, please see [www.arb.ca.gov/ep\\_label](http://www.arb.ca.gov/ep_label).

Protect the environment. Choose vehicles with higher ratings:

Greenhouse Gas Rating (tailpipe only)

A+ CleanerC D

Smog Rating (tailpipe only)

A+ CleanerA D

Using alternative fuels may change scores.

Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle’s measured emissions.

GOVERNMENT 5-STAR SAFETY RATINGS

Overall Vehicle Score

Not Rated

Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size and weight.

Frontal Crash

Driver Passenger

★★★★★

Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and weight.

Side Crash

Front seat Rear seat

Not Rated Not Rated

Based on the risk of injury in a side impact.


Rollover

Not Rated

Based on the risk of rollover in a single-vehicle crash.

Star ratings range from 1 to 5 stars (★★★★★), with 5 being the highest. Source: National Highway Traffic Safety Administration (NHTSA). [www.safercar.gov](http://www.safercar.gov) or 1-888-327-4236


1FTBR3X81SKA07641



WARNING:

Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to [www.P65Warnings.ca.gov/passenger-vehicle](http://www.P65Warnings.ca.gov/passenger-vehicle).

rates may apply. Text HELP for help



[www.ford.com/help/privacy-terms/](http://www.ford.com/help/privacy-terms/)

1202501305255