



ford.com

VEHICLE DESCRIPTION

TRANSIT

2024 350 LR CARGO AWD
148" WHEELBASE
3.5L PFDI V6 (GAS)
10-SPEED TRANSMISSION


RK **B60859**

EXTERIOR
OXFORD WHITE
INTERIOR
DARK PALAZZO GRAY VINYL

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

- | EXTERIOR | INTERIOR | FUNCTIONAL | SAFETY/SECURITY |
|---|---|--|---|
| <ul style="list-style-type: none"> • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • HEADLAMP COURTESY DELAY • WIPERS - RAIN-SENSING | <ul style="list-style-type: none"> • AIR CONDITIONING • ASSIST HANDLE - B-PILLAR • ASSIST HANDLES - A-PILLAR • INTERIOR LIGHTING - LED • LOCKING GLOVE BOX • POWERPOINT - 12V (FRONT) • STEERING - TILT/TELESCOPIC • TACHOMETER | <ul style="list-style-type: none"> • AUTO HIGH-BEAM HEADLAMPS • ELECTRONIC PWR ASST STEER • FORWARD COLLISION WARNING • HILL START ASSIST • LANE-KEEPING SYSTEM • POST-COLLISION BRAKING • PRE-COLLISION ASSIST W/AEB • REAR VIEW CAMERA • W/ TRAILER HITCH ASSIST • SELECTABLE DRIVE MODES • SIDE-WIND STABILIZATION • SUSPENSION - HEAVY DUTY FRONT AXLE | <ul style="list-style-type: none"> • 3 POINT SAFETY BELTS • ADVANCETRAC™ WITH RSC® • AIRBAGS ☐ FRONT, SIDE AND SAFETY CANOPY® SYSTEM • BRAKES - 4WHEEL DISC W/ABS • SECURILOCK® ANTI-THEFT SYS • SOS POST-CRASH ALERT SYS™ • TIRE PRESSURE MONIT SYS |
| | | | WARRANTY |
| | | | <ul style="list-style-type: none"> • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST |

INCLUDED ON THIS VEHICLE		(MSRP)	PRICE INFORMATION		(MSRP)
<u>OPTIONAL EQUIPMENT/OTHER</u>					
PREFERRED EQUIPMENT PKG.101A			BASE PRICE		\$54,630.00
3.73 LIMITED SLIP AXLE	NO CHARGE		TOTAL OPTIONS/OTHER		725.00
REAR COMPARTMENT LIGHTING	75.00				
FRONT LICENSE PLATE BRACKET	NO CHARGE		TOTAL VEHICLE & OPTIONS/OTHER		55,355.00
9500# GVWR PACKAGE	NO CHARGE		DESTINATION & DELIVERY		2,095.00
50 STATE EMISSIONS	NO CHARGE				
REVERSE SENSING SYSTEM	295.00				
RADIO - SYNC3, 4" SCN	280.00				
2 ADDITIONAL KEYS	75.00				
E-85 FLEX FUEL CAPABLE	NO CHARGE				


	RAMP ONE		TOTAL MSRP \$57,450.00
	CD79	RAIL	
	RAMP TWO	ITEM #:	 <p>Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.</p>
		41-X016 O/T 2	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		B830 A 7BX X 450 001658 02 13 25

California Air Resources Board Flexible-Fuel Vehicle Gasoline-Ethanol (E85)

Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings.
For information on how to compare, please see www.arb.ca.gov/ep_label.

Protect the environment. Choose vehicles with **higher ratings**:




Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.




GOVERNMENT 5-STAR SAFETY RATINGS

Overall Vehicle Score	Not Rated
-----------------------	-----------

Based on the combined ratings of frontal, side and rollover.
Should ONLY be compared to other vehicles of similar size and weight.



Based on the risk of injury in a frontal impact.
Should ONLY be compared to other vehicles of similar size and weight.




Based on the risk of injury in a side impact.



Based on the risk of rollover in a single-vehicle crash.

Star ratings range from 1 to 5 stars (★★★★★), with 5 being the highest.
Source: National Highway Traffic Safety Administration (NHTSA).
www.safercar.gov or 1-888-327-4236



 **WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, van or other vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

rates may
apply.
Text HELP
for help



www.ford.com/help/privacy-terms/