FD KAN-003801 AL	9-NORMAL,NB,203801,SF182 13982 12025062	ULC U W CERTCERTCERT TRD RAMPBUMPCAM	030387 PBOOKEXFLROTABATT 606/1919 IFTBW3X83 SKA
Ford	148" WHEELBASE 3.5L PFDI V6 (GAS) INT	SK A93155 TERIOR OXFORD WHITE FERIOR	California Air Resources Board Flexible-Fuel Vehicle Ga Environmental Performan
ford.com STANDARD EQUIPMENT INCLUDED EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • HEADLAMP COURTESY DELAY • WIPERS - RAIN-SENSING		ASST STEER • ADVANCETRAC™ WITH RSC® HON WARNING • AIRBAGS ⊠ FRONT, SIDE AND STEM • BRAKES - 4WHEEL DISC W/ABS BRAKING • SCURILOCK® ANTI-THEFT SYS SSIST W/AEB • SOS POST-CRASH ALERT SYS™ ASSIST • TIRE PRESSURE MONIT SYS WARRANTY • WARRANTY	These ratings are not directly comparable to the U.S. EPA/DOT light-duty ver For information on how to compare, please see www.arb.ca.gov/ Protect the environment. Choose vehicles with high Greenhouse Gas Rating (tailpipe only) C A+ Cleaner Using alternative fuels may change scores.
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.101A 4.10 LIMITED SLIP AXLE RAR COMPARTMENT LIGHTING FRONT LICENSE PLATE BRACKET 9500# GVWR PACKAGE 50 STATE EMISSIONS REVERSE SENSING SYSTEM 2 ADDITIONAL KEYS LOAD AREA PROTECTION PKG .VINYL F/R FLOOR COVERING E-85 FLEX FUEL CAPABLE	(MSRP) NO CHARGE NO CHARGE NO CHARGE 295.00 75.00 S75.00 NO CHARGE	Minimum and any state in the state in t	Vehicle emissions are a primary contributor to climate change and smog. Ratings are de California Air Resources Board based on this vehicle's measured emissions. Image: Control of Control
	RAMP ONE CS15 CS15 CONVOY RAMP TWO CONVOY ITEM #: 21-101X O/T 2 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.	TOTAL MSRP \$57,315.00 Scan The QR Code to get more details about this vehicle Image: Compare the second	Obtice: Nationaring may frame outery forministration (NTTOR): www.safercar.gov or 1-888-327-4236 IFTBW3X83SKA93155 Image: State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

1202506293549



Get Prequalified now at www.ford.com/finance