
	ICLE DESCRIPTION		RK A94	585	California Air Res	sources Boa
ford.com	2024 350 HR CARGO RWD 148" WHEELBASE 3.5L PFDI V6 (GAS) 10-SPEED TRANSMISSION	INTERIOR				vironmer
STANDARD EQUIPMENT INCLUDED A	AT NO EXTRA CHARGE				These ratings are not	<i>i i</i>
EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • HEADLAMP COURTESY DELAY • WIPERS - RAIN-SENSING	INTERIOR • AIR CONDITIONING • ASSIST HANDLES - A-PILLAR • CENTER CONSOLE • INTERIOR LIGHTING - LED • LOCKING GLOVE BOX • POWERPOINT - 12V (FRONT) • STEERING - TILT/TELESCOPIC • TACHOMETER	FUNCTIONAL • AUTO HIGH-BEAM HEADLA • ELECTRONIC PWR ASST ST • FORWARD COLLISION WAR • HILL START ASSIST • LANE-KEEPING SYSTEM • POST-COLLISION BRAKING • PRE-COLLISION BRAKING • REAR VIEW CAMERA W/ TRAILER HITCH ASSIST • SELECTABLE DRIVE MODE • SIDE-WIND STABILIZATION	TEER • ADVANCETRAC™ WIT RNING • AIRBAGS ⊠ FRONT, SI SAFETY CANOPY® SY • BRAKES - 4WHEEL DI • SECURILOCK® ANTI- (AEB • SOS POST-CRASH AL • TIRE PRESSURE MON SS WARRANTY	TH RSC® DE AND 'STEM SC W/ABS THEFT SYS ERT SYS™ IIT SYS / BUMPER BAIN		tion on how to com nvironment. C Rating (tailpipe C
	(MSRP)			(MSRP)	Vehicle emissions are a prim California Air Resources Boa	
OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.101A 4.10 LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET VINYL F/R FLOOR COVERING 9500# GWWR PACKAGE B-PILLAR ASSIST HANDLE 50 STATE EMISSIONS HD TRAILER TOW PACKAGE RADIO - SYNC3, 4" SCN FRONT OVERHEAD SHELF UPFITTER PACKAGE .MODIFIED VEHICLE WIRING SYS .DUAL BATTERIES (70 AMP-HR) .LARGE CENTER CONSOLE .AUXILIARY FUSE PANEL TRAILER BRAKE CONTROLLER DAYTIME RUNNING LAMPS E-85 FLEX FUEL CAPABLE	NO CHARGE 245.00 NO CHARGE 25.00 NO CHARGE 485.00 280.00 75.00 610.00 230.00 45.00 NO CHARGE	BASI TOT, TOT,	CE INFORMATION E PRICE AL OPTIONS/OTHER AL VEHICLE & OPTIONS/OTHER TINATION & DELIVERY	\$53,655.00 1,995.00 55,650.00 2,095.00	Overall Vehicle ScoreBased on the combined ratings of Should ONLY be compared to othFrontal CrashDriver PasserBased on the risk of injury in a fro Should ONLY be compared to othSide CrashFront s Rear se Based on the risk of injury in a sidSide CrashFront s Rear se Based on the risk of injury in a sidBased on the risk of injury in a sidSide CrashFront s Rear se Based on the risk of injury in a sidStar ratings range from 1 to 5 Source: National Highway	f frontal, side and rollover. her vehicles of similar size mger ther vehicles of similar size seat teat teat teat Not Raise single-vehicle crash. stars (* * * * * *), w
	CS15	т	DTAL MSRP \$57,7	45.00		TBW3X88RKA94585
	RAMP TWO	ge	an The QR Code to t more details about is vehicle		WARNING: Operating, servi vehicle can expose you to ch lead, which are known to the State	cing and maintaining a particular sincluding engine
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not i	the Federal Automobile oline, License, and Title Fees, Iuded. Dealer installed BS	914 A 7BX X 435 000392 06 1	25	To minimize exposure, avoid breath vehicle in a well-ventilated area and For more information go to www.P6	ing exhaust, do not idle th 1 wear gloves or wash you 5Warnings.ca.gov/passer



he engine except as necessary, service your ur hands frequently when servicing your vehicle. nger-vehicle.

Get Prequalified now at www.ford.com/finance