VEHI					
(Freedom)	RANGER		^{sL} E21113	EPA DOT Fuel Econom	y and En
Oora	2025 SUPERCREW 4X2 XL 128" WHEELBASE 2.3L ECOBOOST ENGINE	EXTERIOR OXFORD WH INTERIOR	ITE	Fuel Economy	 Standard Pic
ford.com	10-SPEED AUTO TRANSMISSI		TH SEATS		G 87 MPG. Th MPGe.
STANDARD EQUIPMENT INCLUDED A	IT NO EXTRA CHARGE				26
EXTERIOR • DAYTIME RUNNING LAMPS	INTERIOR • 1-TOUCH UP/DOWN DRIVER WIN	FUNCTIONAL • AUDIO - 6 SPEAKERS	SAFETY/SECURITY • AIRBAGS - SAFETY CANOPY®	combined city/hwy city	highway
EASY FUEL® CAPLESS FILLER	10" CENTER TOUCHSCREEN	• AUDIO - 6 SPEAKERS • BRAKES - ANTI-LOCK SYSTEM	• BELT-MINDER CHIME		
• FENDER BADGE	2ND ROW FOLD BENCH	ELECTRIC PARKING BRAKE	CTR HIGH MOUNT STOP LAMP	4.3 gallons per 100 miles	
FULL SIZE SPARE TIRE/WHEEL FULLY BOXED STEEL FRAME		INDEPENDENT FRONT SUSPEN PRE-COLLISION ASSIST W/AEB	• LATCH CHILD SAFETY SYSTEM • PASSIVE ANTI-THEFT SYSTEM		
GRILLE - BLACK	DUAL SUNVISORS	REAR VIEW CAMERA	TIRE PRESSURE MONIT SYS		Fuel Economy 8
HEADLAMPS - AUTO ON/OFF PICKUP BOX TIE DOWN HOOKS	LOCKING GLOVE BOX POWER LOCKS AND WINDOWS	REMOTE KEYLESS ENTRY SELECTSHIFT®	WARDANTY	Annual fuel COST	
REMOTE TAILGATE LOCK	POWER LOCKS AND WINDOWS POWERPOINTS-12V, USB	• SELECTSHIFT® • SYNC®4A	• 3YR/36.000 BUMPER / BUMPER		
WHEEL LIP MOLDINGS	• SEATS - MANUAL		• 5YR/60,000 POWERTRAIN	むつ つへへ	1
• WIPERS- INTERMITTENT	TILT/TELESCOPE STR COLUMN		5YR/60,000 ROADSIDE ASSIST	\$2,300	
					This vehicle emits 387
					distributing fuel also cr
				Actual results will vary for many reasons,	including driving co
				Actual results will vary for many reasons, vehicle. The average new vehicle gets 28 based on 15,000 miles per year at \$3.50 p emissions are a significant cause of clima	MPG and costs \$9,50 er gallon. MPGe is m
INCLUDED ON THIS VEHICLE	(MSRP)		(MSRP)	emissions are a significant cause of clima	te change and smog.
EQUIPMENT GROUP 100A		PRICE INFO		fueleeenomya	\sim
•XL SERIES		BASE PRICE	E \$33,080.00 IONS/OTHER 640.00	fueleconomy.g	UV
OPTIONAL EQUIPMENT/OTHER		TOTAL OF	040.00	Calculate personalized estimates and o	compare vehicles
255/70 R17 A/T TIRE			ICLE & OPTIONS/OTHER 33,720.00		
STX APPEARANCE PACKAGE	NO CHARGE	DESTINATIO	ON & DELIVERY 1,595.00	GOVERNMENT 5-S	IAR SAFELY
.FOG LAMPS .17" SILVER PAINTED ALUM WHL				Overall Vehicle Score	+ + .
FRONT LICENSE PLATE BRACKET	NO CHARGE				I side and rollover
CARPET FLOORING	145.00			Based on the combined ratings of fronta Should ONLY be compared to other veh	icles of similar size a
BEDLINER-TOUGHBED SPRAY-IN	495.00				
					A A
				Frontal Driver	$\begin{array}{c} \star \star \\ \star \star \end{array}$
				Crash Passenger	
				Based on the risk of injury in a frontal im Should ONLY be compared to other veh	ipact.
				Snould UNLY be compared to other veh	icies of similar size a
				Side Front seat	**
				Crash Rear seat	$\begin{array}{c} \star \star \\ \star \star \end{array}$
				Based on the risk of injury in a side impa	
				based on the lisk of injury in a side impa	
				Rollover	$\star \star \star$
				Based on the risk of rollover in a single-	
				Star ratings range from 1 to 5 stars	(
				Source: National Highway Traf	fic Safety Admini
					ov or 1-888-327-4
				www.salercal.g	
	RAMP ONE	ТОТА	MEDD	1FTER4	BH2SLE21113
		ΤΟΤΑΙ	L MSRP \$35,315.00		
	RAMP ONE RH80				
			Whether you decide to lease or finance your		BH2SLE21113
	RH80	RAIL	Whether you decide to lease or finance your vehicle, you'll find the choices that are right		BH2SLE21113
	RH80	RAIL	Whether you decide to lease or finance your vehicle, you'll find the choices that are right to ryou. See your dealer for details or visit		BH2SLE21113
	RH80	RAIL 52-8054 O/T 5C	Whether you decide to lease or finance your vehicle, you'll find the choices that are right	WARNING: Operating, servicing an vehicle can expose you to chemica lead, which are known to the State of Cali	BH2SLE21113 d maintaining a pass ls including engine ex fornia to cause cance
	RH80 RAMP TWO ITEM # This label is affixed pursuant to	RAIL 52-8054 O/T 5C the Federal Automobile	Whether you decide to lease or finance your vehicle, you'll find the choices that are right t for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing an vehicle can expose you to chemica lead, which are known to the State of Cali To minimize exposure, avoid breathing ex	BH2SLE21113 d maintaining a pass ls including engine ex- fornia to cause cance haust do not idle the
	RH80 RAMP TWO ITEM # This label is affixed pursuant to Information Disclosure Act. Ga	RAIL First 52-8054 O/T 5C Ford Credi the Federal Automobile soline, License, and Title Fees,	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing an vehicle can expose you to chemica lead, which are known to the State of Cali To minimize exposure, avoid breathing ex	BH2SLE21113 d maintaining a pass ls including engine ex- fornia to cause cance haust do not idle the
	RH80 RAMP TWO ITEM # This label is affixed pursuant to	RAIL 52-8054 O/T 5C The Federal Automobile isoline, License, and Title Fees, icluded. Dealer installed	Whether you decide to lease or finance your vehicle, you'll find the choices that are right t for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing an vehicle can expose you to chemica lead, which are known to the State of Cali	BH2SLE21113 d maintaining a pass ls including engine ex- fornia to cause cance haust do not idle the

