			^{sl} E21	400	EDA	
C C C C C C C C C C C C C C C C C C C	RANGER			180	EPA DOT Fuel Economy a	Ind Env
(Jord)	2025 SUPERCREW 4X2 XL 128" WHEELBASE	EXTERIOR OXFORD	WHITE		Fuel Economy	
	2.3L ECOBOOST ENGINE	INTERIOR				Standard Pic
ford.com	10-SPEED AUTO TRANSMISS	SION EBONY C	LOTH SEATS			87 MPG. Th MPGe.
STANDARD EQUIPMENT INCLUDED A	T NO EXTRA CHARGE					26
EXTERIOR	INTERIOR	FUNCTIONAL	SAFETY/SECURITY			∠ Vighway
DAYTIME RUNNING LAMPS	1-TOUCH UP/DOWN DRIVER WIN	• AUDIO - 6 SPEAKERS	AIRBAGS - SAFETY			
EASY FUEL® CAPLESS FILLER FENDER BADGE	10" CENTER TOUCHSCREEN 2ND ROW FOLD BENCH	 BRAKES - ANTI-LOCK SYSTEM ELECTRIC PARKING BRAKE 	 Image: BELT-MINDER CHIN Image: CTR HIGH MOUNT \$ 		4.3 gallons per 100 miles	
FULL SIZE SPARE TIRE/WHEEL	CRUISE CONTROL	INDEPENDENT FRONT SUSPER			T ∎ J gallons per 100 miles	
FULLY BOXED STEEL FRAME	DIGITAL INSTRUMENT CLUSTER	 PRE-COLLISION ASSIST W/AE 	B • PASSIVE ANTI-THEF			
• GRILLE - BLACK	DUAL SUNVISORS	REAR VIEW CAMERA	TIRE PRESSURE MO	ONIT SYS	Fue	I Economy 8
HEADLAMPS - AUTO ON/OFF PICKUP BOX TIE DOWN HOOKS	LOCKING GLOVE BOX POWER LOCKS AND WINDOWS	REMOTE KEYLESS ENTRY SELECTSHIFT®	WARRANTY		Annual fuel COST	
REMOTE TAILGATE LOCK	POWER LOCKS AND WINDOWS POWERPOINTS-12V, USB	• SYNC®4A	• 3YR/36,000 BUMPE	R / BUMPER		
• WHEEL LIP MOLDINGS	SEATS - MANUAL	••••••	• 5YR/60,000 POWER		¢2 200 6	
WIPERS- INTERMITTENT	TILT/TELESCOPE STR COLUMN		• 5YR/60,000 ROADSI	DE ASSIST	\$2,300 ₽	
						abiele ensite 207
						ehicle emits 387 gouting fuel also cre
					Actual results will vary for many reasons, inclu- vehicle. The average new vehicle gets 28 MPG	and costs \$9,50
	(84000)		11		Actual results will vary for many reasons, inclu vehicle. The average new vehicle gets 28 MPG a based on 15,000 miles per year at \$3.50 per gal emissions are a significant cause of climate cha	lon. MPGe is mi
INCLUDED ON THIS VEHICLE	(MSRP)			(MSRP)	emissions are a significant cause of climate cha	inge and smog.
EQUIPMENT GROUP 100A			INFORMATION	¢00.000.00	fueleconomy.gov	7
•XL SERIES		BASE P	RICE OPTIONS/OTHER	\$33,080.00 640.00		
OPTIONAL EQUIPMENT/OTHER		TOTAL	of hono, official	040.00	Calculate personalized estimates and compa	are vehicles
255/70 R17 A/T TIRE			VEHICLE & OPTIONS/OTHER	33,720.00		
STX APPEARANCE PACKAGE	NO CHARGE	DESTIN	ATION & DELIVERY	1,595.00	GOVERNMENT 5-STAF	SAFEIY
.FOG LAMPS						
.17" SILVER PAINTED ALUM WHL FRONT LICENSE PLATE BRACKET	NO CHARGE				Overall Vehicle Score	$\star \star \gamma$
CARPET FLOORING	145.00				Based on the combined ratings of frontal, side Should ONLY be compared to other vehicles of	and rollover.
BEDLINER-TOUGHBED SPRAY-IN	495.00				Should ONLY be compared to other vehicles of	oi similar size ai
					Frontal Driver	_
						★ ★ ↑ ★ ★ ↑
					Crash Passenger	
					Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of	
					Should ONLY be compared to other vehicles	of similar size a
					Side Front seat	<u> </u>

					Crash Rear seat	$\star \star \star$
					Based on the risk of injury in a side impact.	
					Rollover	$\star \star \star$
					Based on the risk of rollover in a single-vehicle	e crash.
					Star ratings range from 1 to 5 stars (\star	
					Source: National Highway Traffic S	
					www.safercar.gov or	° 1-888-327-42
	BAMP ONE		AL MSRP \$35,	315.00	1FTER4BH6S	LE21180
	RAMP ONE					
		ТОТ	AL WISHP \$35,			
	RAMP ONE RH80					
			Whether you decide to leas	se or finance your		
	RH80	RAIL	Whether you decide to lease vehicle, you'll find the choi	se or finance your ces that are right	WARNING: Operating, servicing and ma	intaining a pass
	RH80	RAIL Toro	Whether you decide to lease vehicle, you'll find the choi redit for you. See your dealer for	se or finance your ces that are right	WARNING: Operating, servicing and ma	intaining a pass
	RH80	RAIL	Whether you decide to leas	se or finance your ces that are right	WARNING: Operating, servicing and ma vehicle can expose you to chemicals included which are known to the State of California	intaining a pass uding engine ex
	RH80	RAIL 52-8064 O/T 5C Ford Cr	Whether you decide to lease vehicle, you'll find the choi redit for you. See your dealer for	se or finance your ces that are right	WARNING: Operating, servicing and ma vehicle can expose you to chemicals incl lead, which are known to the State of California	intaining a pass uding engine ex to cause cance do not idle the
	RH80	RAIL #: 52-8064 O/T 5C to the Federal Automobile	Whether you decide to leasy vehicle, you'll find the choi redit for you. See your dealer for www.ford.com/finance.	se or finance your ces that are right details or visit	WARNING: Operating, servicing and ma vehicle can expose you to chemicals incl lead, which are known to the State of California To minimize exposure, avoid breathing exhaust, vehicle in a well ventilated area and wear glave	intaining a pass uding engine ex to cause cance do not idle the
	RH80	RAIL #: 52-8064 O/T 5C to the Federal Automobile Gasoline, License, and Title Fees, iscladed a Declarization and Title Fees,	Whether you decide to lease vehicle, you'll find the choi for you. See your dealer for www.ford.com/finance.	se or finance your ces that are right details or visit	WARNING: Operating, servicing and ma vehicle can expose you to chemicals incl lead, which are known to the State of California To minimize exposure, avoid breathing exhaust, vehicle in a well-ventilated area and wear glove	intaining a pass uding engine ex to cause cance do not idle the s or wash your h
	RH80 RAMP TWO ITEM This label is affixed pursuant Information Disclosure Act. OS State and Local taxes are not	RAIL #: 52-8064 O/T 5C to the Federal Automobile Gasoline, License, and Title Fees, iscladed a Declarization and Title Fees,	Whether you decide to leasy vehicle, you'll find the choi redit for you. See your dealer for www.ford.com/finance.	se or finance your ces that are right details or visit	WARNING: Operating, servicing and ma vehicle can expose you to chemicals incl lead, which are known to the State of California To minimize exposure, avoid breathing exhaust, vehicle in a well-ventilated area and wear glove For more information go to www.P65Warnings.c	intaining a pass uding engine ex to cause cance do not idle the s or wash your h ca.gov/passenge

