



Go Further

ford.com

VEHICLE DESCRIPTION

RANGER

2022 SUPERCREW 4X4 - 5' BOX
 LARIAT 126" WHEELBASE
 2.3L ECOBOOST ENGINE
 ELEC 10-SPEED AUTO TRANS

NL **D00717**

EXTERIOR
 VELOCITY BLUE

INTERIOR
 EBONY LEATHER-TRIMMED SEATS

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

INTERIOR

FUNCTIONAL

SAFETY/SECURITY

WARRANTY

INCLUDED ON THIS VEHICLE		(MSRP)	
<u>EQUIPMENT GROUP 501A</u>			
•LARIAT SERIES			
•TECHNOLOGY PACKAGE			
•B&O,10-SPKRS,HD,SXM,SYNC3,NAV			
•ADAPTIVE CRUISE CONTROL			
•FORWARD SENSING SYSTEM			
•REMOTE START			
<u>OPTIONAL EQUIPMENT/OTHER</u>		<u>PRICE INFORMATION</u>	
265/60R18 OFF-RD A/T OWL TIRE		BASE PRICE	\$39,250.00
FX4 OFF-ROAD PACKAGE	1,295.00	TOTAL OPTIONS/OTHER	6,660.00
.OFF-ROAD TUNED SUSPENSION			
.TRAIL CONTROL SYSTEM			
.SKID PLATES			
.ELECTRONIC-LOCKING DIFF			
BLACK APPEARANCE PACKAGE	1,995.00		
.18" BLACK PAINTED ALUM WHEEL			
.BEDLINER-TOUGHBED SPRAY-IN			
.RUNNING BOARDS-5" RECT-BLACK			
SPLASH GUARDS/MUD FLAPS FR/RR	130.00		
FLR LINERS ALL WTHR+CRPT MATS	200.00		
ENGINE BLOCK HEATER	90.00		
BLACK GRAPHIC	450.00		
TRAILER TOW PACKAGE	495.00		
FRONT LICENSE PLATE BRACKET	NO CHARGE		
		TOTAL VEHICLE & OPTIONS/OTHER	45,910.00
		DESTINATION & DELIVERY	1,295.00

	RAMP ONE RA8F	RAIL ITEM #: 11-1652 O/T 2	TOTAL MSRP \$47,205.00
	RAMP TWO		 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. FORD CREDIT
This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.			MM101 N RB 2X 215 001404 12 10 21

EPA DOT Fuel Economy and Environment



Gasoline Vehicle

www.ford.com/help/privacy-terms/



 **WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.