			sl <b>E386</b>	571	EPA DOT Fuel Economy and En
Ford.com	2025 SUPERCREW 4X4 XLT 128" WHEELBASE 2.3L ECOBOOST ENGINE 10-SPEED AUTO TRANSMISS	INTERIOF	R ONIZED GRAY METALLIC		Fuel Economy Fuel Economy MPG Standard P 87 MPG. T MPGe.
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FENDER BADGE • FOG LAMPS • FULL SIZE SPARE TIRE/WHEEL • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • LED REFLECTOR HEADLAMPS • PRIVACY GLASS REMOTE TAILGATE LOCK • TAILLAMPS-LED • WHEEL LIP MOLDINGS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 301A • XLT SERIES • POWER SLIDING REAR WINDOW • DUAL-ZONE ELEC CLIMATE CONTRO OPTIONAL EQUIPMENT/OTHER 255/65R 18 A/T TIRE FX4 OFF-ROAD PACKAGE .OFF-ROAD TUNED SHOCKS .3.73 LOCKING RR DIFFERENTIAL BLACK APPEARANCE PACKAGE .0FF-ROAD TUNED SHOCKS .3.73 LOCKING RR DIFFERENTIAL BLACK APILE XLT TECHNOLOGY PACKAGE .ADAPTIVE CRUISE CONTROL .360-DEGREE CAMERA FRONT LICENSE PLATE BRACKET FLR LINERS ALL WTHR+CRPT MATS RUNNING BOARDS - BLACK TRAILER TOW PACKAGE BEDLINER-DROP-IN DEALER INSTALLED OPTIONS SecuriCodeÖ Wireless Keyless E	NO EXTRA CHARGE INTERIOR 1.170UCH UP/DOWN DRIVER WIN 2ND ROW FOLD BENCH 2ND ROW UNDER SEAT STORAGE AUTO-DIM REARVIEW MIRRORS DIGITAL INSTRUMENT CLUSTER DUAL VISOR VANITY MIRRORS LOCKING GLOVE BOX POWER LOCKS AND WINDOWS POWER POINTS-12V, USB TILT/TELESCOPE STR COLUMN 1,195.00 1,195.00 1,100.00 225.00	BAS TOT TOT	• CTR HIGH MOUNT STO   • LATCH CHILD SAFETY   • LATCH CHILD SAFETY   • PASSIVE ANTI-THEFT   • TIRE PRESSURE MONI   • WARRANTY	DP LAMP SYSTEM SYSTEM T SYS BUMPER AIN	And the second s
	RAMP ONE CE4G	т	OTAL MSRP \$48,0	35.00	
	RAMP TWO	#: ge	can The QR Code to et more details about is vehicle		WARNING: Operating, servicing and maintaining a pa vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can
	State and Local taxes are not	to the Federal Automobile Basoline, License, and Title Fees,	F031 N RB 2X 530 010061 06 03		lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passen

