МІС-004791 ок	9-NORMAL,NB,104791,SF101 85	61 320250618 3765		V OK MPBUMPCAM	PBOOKEXFLROTABATT 94/
VEH	ICLE DESCRIPTION RANGER 2025 SUPERCREW 4X4 XLT 128" WHEELBASE 2.3L ECOBOOST ENGINE 10-SPEED AUTO TRANSMISSIC	EXTERIOR VELOCITY BI INTERIOR EBONY CLO EUNCTIONAL AUDIO - 6 SPEAKERS BLIS W/CROSS TRAFFIC ALERT BRAKES - ANTI-LOCK SYSTEM LANE KEEPING SYSTEM PRE-COLLISION ASSIST W/AEB PRE-COLLISION ASSIST W/AEB PRE-COLLISION ASSIST W/AEB PRE-COLLISION ASSIST W/AEB BRAMOTE KEYLESS ENTRY REMOTE START SYSTEM SIRIUSXM® - SVC N/A AK&HI SYNC®4A PRICE INFO BASE PRICE TOTAL OPT TOTAL VEH DESTINATION	SL E29494 TERIOR VELOCITY BLUE METALLIC ERIOR EBONY CLOTH SEATS SAFFIC ALERT CK SYSTEM SIST W/AEB SAFFIC MICHILD SAFETY SYSTEM SIST W/AEB SA ENTRY STEM WARRANTY		
.17" GRAY PTD ALUM WHL-SPORT .GRAY GRILLE FRONT LICENSE PLATE BRACKET FLR LINERS ALL WEATHER MATS RUNNING BOARDS - BLACK TRAILER TOW PACKAGE DEALER INSTALLED OPTIONS SecuriCodeÖ Wireless Keyless E	NO CHARGE 160.00 750.00 535.00 225.00		VINGS	- 750.00	Frontal CrashDriver Passenger* * * *Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size arSide CrashFront seat Rear seatBased on the risk of injury in a side impact.Based on the risk of injury in a side impact.RolloverBased on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (*****), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-42
	RAMP ONE RPTB RAMP TWO ITEM #:	RAIL Scan T	MSRP \$43,2 The QR Code to the details about	75.00	IFTER4HH4SLE29494 WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine expose you to chemicals including engine expose Lead which are known to the State of California to cause cance
	This label is affixed pursuant to t Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not in	the Federal Automobile oline, License, and Title Fees, Juded. Dealer installed SF101 N	RB 2X 530 004791 06 10	25	lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

