MIC-006860 <sub>CA</sub>	9-NORMAL, NB, 106860, SD231 942	28 320250502 5429 BLEND 5429	ULC         U         W         CA           CERTCERTCERT         TRD         RAMPBUMPCAN	IPBOOKEXFLROTABATT 2675
Ford.com	IICLE DESCRIPTION <b>RANGER</b> 2025 SUPERCREW 4X4 XLT 128" WHEELBASE 2.7L ECOBOOST ENGINE 10-SPEED AUTO TRANSMISSION	INTERIOR	SL E17293 d gray metallic th seats	EPA DOT       Fuel Economy and Environment         Fuel Economy       MPG         Tomation       MPG.
STANDARD EQUIPMENT INCLUDED EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FENDER BADGE • FOG LAMPS • FULL SIZE SPARE TIRE/WHEEL • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • LED REFLECTOR HEADLAMPS • PRIVACY GLASS • REMOTE TAILGATE LOCK • TAILLAMPS-LED • WHEEL LIP MOLDINGS	AT NO EXTRA CHARGE INTERIOR - 1-TOUCH UP/DOWN DRIVER WIN - 2ND ROW FOLD BENCH - 2ND ROW UNDER SEAT STORAGE - AUTO-DIM REARVIEW MIRROR - AUTO-DIM REARVIEW MIRROR - OLITAL INSTRUMENT CLUSTER - DUAL VISOR VANITY MIRRORS - DUAL VISOR VANITY MIRRORS - DOWER LOCKS AND WINDOWS - POWERPOINTS-12V, USB - TILT/TELESCOPE STR COLUMN	FUNCTIONAL • AUDIO - 6 SPEAKERS • BLIS W/CROSS TRAFFIC ALERT • BRAKES - ANTI-LOCK SYSTEM • LANE KEEPING SYSTEM • PRE-COLLISION ASSIST W/AEB • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • REMOTE START SYSTEM • SIRIUSXM® - SVC N/A AK&HI • SYNC®4A	SAFETY/SECURITY • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • CTR HIGH MOUNT STOP LAMP • LATCH CHILD SAFETY SYSTEM • PASSIVE ANTI-THEFT SYSTEM • TIRE PRESSURE MONIT SYS MARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST	<ul> <li>including the solution of the solutical solution of the solution of the solution of the solution</li></ul>
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 301A •XLT SERIES •POWER SLIDING REAR WINDOW •DUAL-ZONE ELEC CLIMATE CONTRO OPTIONAL EQUIPMENT/OTHER 2.7L ECOBOOST ENGINE 255/65R 18 A/T TIRE 4X4 REGIONAL DISCOUNT PKG FX4 OFF-ROAD DACKAGE .OFF-ROAD TUNED SHOCKS .3.73 LOCKING RR DIFFERENTIAL BLACK APPEARANCE PACKAGE .18" BLACK PAINTED ALUM WHEEL .BLACK GRILLE ADVANCED TOW PKG + TECH PKG .PROTRAILER B/UP ASSIST W/TBC .ADAPTIVE CRUISE CONTROL .360-DEGREE CAMERA FRONT LICENSE PLATE BRACKET INTEGRATED BOX SIDE STEP TRAILER TOW PACKAGE	(MSRP) 1,100.00 2,195.00 NO CHARGE 1,095.00 1,845.00 NO CHARGE 215.00 NO CHARGE		CORMATION TIONS/OTHER NICLE & OPTIONS/OTHER ON & DELIVERY EFORE DISCOUNTS IONAL DISCOUNT P AVINGS - 250.00	Actual results will vary for many reasons, including driving correlation. The average new vehicle gets 28 MPG and costs \$9,500 based on 15,000 miles per year at \$3.50 per gallon. MPGe is milemissions are a significant cause of climate change and smog. <b>Gueleconogygov</b> Calculate personalized estimates and compare vehicles <b>GOVERNMENT 5-STAR SAFETY Overall Vehicle Score Actual Personalized estimates and compare vehicles Based on the combined ratings of frontal, side and rollover.</b> Should ONLY be compared to other vehicles of similar size and <b>Frontal</b> Driver <b>Crash</b> Passenger         Based on the risk of injury in a frontal impact.         Should ONLY be compared to other vehicles of similar size and <b>Side</b> Front seat <b>Crash</b> Rear seat <b>Based on the risk of injury in a side impact</b> .         Should ONLY be compared to other vehicles of similar size and <b>Side</b> Front seat <b>Crash</b> Rear seat         Based on the risk of injury in a side impact.         Should ONLY be compared to other vehicles of similar size and <b>Side</b> Front seat <b>Crash</b> Rear seat         Based on the risk of injury in a side impact.         Based on the risk of rollover in a single-v
	RAMP ONE RA84 RAMP TWO ITEM #:	RAIL	L MSRP \$48,285.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	vehicle can expose you to chemicals including engine e
	This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not inc	line, License, and Title Fees, uded. Dealer installed SD231 I	N RB 2X 520 006860 04 23 25	lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

