МІС-009516 он	9-NORMAL, NB, 109516, SB031 105	566 320250211 1214	CERT CERT CERT TRD RAMP BUMP	CAMPBOOKEXFLROTA 0
	<section-header>Augustation of the second sec</section-header>	EXTERIOR RUBY RED ME INTERIOR EBONY CLOTH AUDIO - 6 SPEAKERS BLIS W/CROSS TRAFFIC ALERT BRAKES - ANTI-LOCK SYSTEM BRAKES - ANTI-LOCK SYSTEM LANE KEEPING SYSTEM BREAR VIEW CAMERA REAR VIEW CAMERA REAR VIEW CAMERA BREMOTE KEYLESS ENTRY REMOTE START SYSTEM SIRIUSXM® - SVC N/A AK&HI SYNC®4A	SL EO64.59 TINTO CLEARCOAT TINTO CLEARCOAT SEATS SAFETY/SECURITY AIRBAGS - SAFETY CANOPY® - BELT-MINDER CHIME - CTR HIGH MOUNT STOP LAMP - LATCH CHILD SAFETY SYSTEM - PASSIVE ANTI-THEFT SYSTEM - SYR/60,000 BUMPER / BUMPER - SYR/60,000 POWERTRAIN - SYR/60,000 ROADSIDE ASSIST - CMSRP - MATION NS/OTHER - S39,495.00 - 7,300.00 LE & OPTIONS/OTHER - 46,795.00	Image: poor (a) and point (a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c
	1,095.00 680.00 825.00 695.00 215.00 NO CHARGE		Frontal CrashDriver PassengerBased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size atSide CrashFront seat Rear seatBased on the risk of injury in a side impact.Based on the risk of injury in a side impact.Rollover Based on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (*****), wi Source: National Highway Traffic Safety Admini www.safercar.gov or 1-888-327-44	
	RAMP ONE CO4G	TOTAL	MSRP \$48,390.00	
	RAMP TWO		Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a pase vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance
	This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not inclu	line, License, and Title Fees, uded. Dealer installed SB031 N F	SB031 N RB 2X 515 009516 02 03 25	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

