|   |   |   | s∟ E39655   |  |
|---|---|---|---|--|
| ford.com STANDARD EQUIPMENT INCLUDED AT EXTERIOR  | RANGER<br>2025 SUPERCREW 4X4 XLT<br>128" WHEELBASE<br>2.7L ECOBOOST ENGINE<br>10-SPEED AUTO TRANSMISSI  | INTERIOR  | T TNTD CLEARCOAT  | Fuel Economy and E<br>Fuel Economy<br>MPG Standard<br>87 MPG.<br>19 23   |
| <ul> <li>DAYTIME RUNNING LAMPS</li> <li>EASY FUEL® CAPLESS FILLER</li> <li>FENDER BADGE</li> <li>FOG LAMPS</li> <li>FULL SIZE SPARE TIRE/WHEEL</li> <li>FULLY BOXED STEEL FRAME</li> <li>HEADLAMPS - AUTO HIGH BEAM</li> <li>LED REFLECTOR HEADLAMPS</li> <li>PRIVACY GLASS</li> <li>REMOTE TAILGATE LOCK</li> <li>TAILLAMPS-LED</li> </ul>   | <ul> <li>1-TOUCH UP/DOWN DRIVER WIN</li> <li>2ND ROW FOLD BENCH</li> <li>2ND ROW UNDER SEAT STORAGE</li> <li>AUTO-DIM REARVIEW MIRROR</li> <li>CARPET FLOORING</li> <li>DIGITAL INSTRUMENT CLUSTER</li> <li>DUAL VISOR VANITY MIRRORS</li> <li>LOCKING GLOVE BOX</li> <li>POWER LOCKS AND WINDOWS</li> <li>POWERPOINTS-12V, USB</li> <li>TILT/TELESCOPE STR COLUMN</li> </ul> | <ul> <li>AUDIO - 6 SPEAKERS</li> <li>BLIS W/CROSS TRAFFIC ALERT</li> <li>BRAKES - ANTI-LOCK SYSTEM</li> <li>LANE KEEPING SYSTEM</li> <li>PRE-COLLISION ASSIST W/AEB</li> <li>REAR VIEW CAMERA</li> <li>REMOTE KEYLESS ENTRY</li> <li>REMOTE START SYSTEM</li> <li>SIRIUSXM® - SVC N/A AK&amp;HI</li> <li>SYNC®4A</li> </ul> | AIRBAGS - SAFETY CANOPY®     BELT-MINDER CHIME     CTR HIGH MOUNT STOP LAMP     LATCH CHILD SAFETY SYSTEM     PASSIVE ANTI-THEFT SYSTEM     TIRE PRESSURE MONIT SYS      WARRANTY     3YR/36,000 BUMPER / BUMPER     5YR/60,000 POWERTRAIN     5YR/60,000 ROADSIDE ASSIST | combined city/hwy city highway<br>5.0 gallons per 100 miles<br>Annual fuel COST<br>\$2,600   |
| • WHEEL LIP MOLDINGS<br>INCLUDED ON THIS VEHICLE<br>EQUIPMENT GROUP 301A  | (MSRP)<br>1,250.00  | PRICE INFO  |   | Actual results will vary for many reasons, including driving<br>vehicle. The average new vehicle gets 28 MPG and costs \$<br>based on 15,000 miles per year at \$3.50 per gallon. MPGe<br>emissions are a significant cause of climate change and so   |
| •XLT SERIES<br>•POWER SLIDING REAR WINDOW<br>•DUAL-ZONE ELEC CLIMATE CONTRO   | 610   | BASE PRICE<br>TOTAL OPTIO   | \$39,845.00<br>NS/OTHER 7,430.00  | fueleconomy.gov<br>Calculate personalized estimates and compare vehicle  |
| OPTIONAL EQUIPMENT/OTHER<br>2025 MODEL YEAR<br>RUBY RED MET TNTD CLEARCOAT<br>2.7L ECOBOOST ENGINE<br>255/65R 18 A/T TIRE<br>BLACK APPEARANCE PACKAGE<br>.18" BLACK PAINTED ALUM WHEEL<br>.BLACK GRILLE<br>ADVANCED TOW PKG + TECH PKG<br>.PROTRAILER B/UP ASSIST W/TBC<br>.ADAPTIVE CRUISE CONTROL<br>.360-DEGREE CAMERA<br>FRONT LICENSE PLATE BRACKET<br>RUNNING BOARDS - BLACK<br>TRAILER TOW PACKAGE | 495.00<br>2,195.00<br>895.00<br>1,845.00<br>NO CHARGE<br>750.00<br>NO CHARGE  |   |   | Overall Vehicle ScoreImage: Additional state of the combined ratings of frontal, side and rollow. Should ONLY be compared to other vehicles of similar states of the compared to other vehicles of similar states.Frontal<br>CrashDriver<br>PassengerBased on the risk of injury in a frontal impact.<br>Should ONLY be compared to other vehicles of similar states.Side<br>CrashFront seat<br>Rear seatBased on the risk of injury in a side impact.Based on the risk of injury in a side impact.Based on the risk of injury in a side impact.Based on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (*****)<br>Source: National Highway Traffic Safety Addres |
|   | RP2P  | TOTAL   |   | 1FTER4HP9SLE39655  |
|   | RAMP TWO  |   | re QR Code to   | WARNING: Operating, servicing and maintaining a vehicle can expose you to chemicals including engired which are known to the State of California to cause can  |
|   | This label is affixed pursuant to<br>Information Disclosure Act. Ga<br>State and Local taxes are not in<br>options or accessories are not   | the Federal Automobile<br>soline, License, and Title Fees,<br>cluded. Dealer installed SF092 N I  | RB 2X 530 001919 06 09 25   | lead, which are known to the State of California to cause c<br>To minimize exposure, avoid breathing exhaust, do not idle<br>vehicle in a well-ventilated area and wear gloves or wash<br>For more information go to www.P65Warnings.ca.gov/pass   |

