MIC-006205 _{MD}	9-NORMAL,NB,006205,SC251	2504 320250404 24	148 CERT CERT CEI	TRD RAMP BUMP C.	AMP BOOK EXFL ROTA	02 240
	ICLE DESCRIPTION RANGER 2025 SUPERCREW 4X4 LARIA 128" WHEELBASE 2.3L ECOBOOST ENGINE 10-SPEED AUTO TRANSMISS AT NO EXTRA CHARGE	MARS INTERIO	R H GRAY	11198 s	EPA DOT Fuel Economy Fuel Economy MI 10	PG Standard Pic 84 MPG. The MPGe.
EXTERIOR • EASY FUEL® CAPLESS FILLER • FENDER BADGE • FOG LAMPS • FULL SIZE SPARE TIRE/WHEEL • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • MIRRORS - PWR / SIGNAL IND • POWER SLIDING REAR WINDOW • PROJECTOR HEADLAMPS LED • REMOTE TAILGATE LOCK • TAILLAMPS-LED • WHEEL LIP MOLDINGS • WIPERS - RAIN-SENSING • WIPERS - RAIN-SENSING • UIPERS - RAIN-SENSING • LARIAT SERIES • OPTIONAL EQUIPMENT/OTHER 255/65R 18 A/T TIRE SPORT APPEARANCE PACKAGE .18" MACH ALUM WHL/DRK POCKET .GRAY GRILLE FRONT LICENSE PLATE BRACKET RUNNING BOARDS - BLACK BEDLINER-TOUGHBED SPRAY-IN	C.A.		 BELT-MINDER CHIME CTR HIGH MOUNT STOP LAM LATCH CHILD SAFETY SYSTE PASSIVE ANTI-THEFT SYSTE TIRE PRESSURE MONIT SYS WARRANTY 3YR/36,000 BUMPER / BUMP 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIS 		Annual fuel Cost \$2,4000 Fuel Economy 8 \$2,4000 Image: Second State	
	RAMP ONE	T	OTAL MSRP	\$50,150.00	Based on the risk of injury in a side im Rollover Based on the risk of rollover in a single Star ratings range from 1 to 5 star Source: National Highway Tr www.safercar	npact. $\star \star \star$ le-vehicle crash. ars ($\star \star \star \star \star$), wit
	CX4G RAMP TWO	CONVOY	Whether you decid	e to lease or finance your the choices that are right ealer for details or visit	WARNING: Operating, servicing vehicle can expose you to chemi	and maintaining a pass icals including engine ex
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		SPECIAL ORDER SC251 N RB 2X 520 006205 03 25 25		lead, which are known to the State of C To minimize exposure, avoid breathing vehicle in a well-ventilated area and we For more information go to www.P65Wa	alifornia to cause cancer exhaust, do not idle the e ear gloves or wash your h

3202504042448

